

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	--

04/28/2017 N24FS S/N: 2040

Hobbs: 1503.2 ACTT: 15446.0

1. Disconnected engine drive shaft and removed transmission assy. From airframe.
2. Removed isolation mount and installed modified isolation mount P/N: 206-030-539-101KF S/N: LK11506 from Aero Products.
 - a. See 8130-3 tracking number W12947-2
3. Removed drag pin assy, and installed new drag pin assy, P/N: 2AA031-509-103 S/N: 15335-041 from Aero Products.
 - a. See 8130-3 tracking number Q3-2016-23315
4. Removed both transmission support link assys, P/N: 206-031-589-001 S/N's: RE3985, 2326 and sent to Aero Products for repair
5. Removed deck mount transmission fittings assys, P/N's 206-031-592-001 S/N: CT0108, 206-031-593-001 S/N: CT0051, 206-031-592-002 S/N: CT0082, 206-031-593-002 S/N: CT0177 and sent to Aero Products for repair
6. Installed repaired deck mount transmission fittings assys, P/N's 206-031-592-001 S/N: CT0108, 206-031-593-001 S/N: CT0051, 206-031-592-002 S/N: CT0082, 206-031-593-002 S/N: CT0177 from Aero Products
 - a. See 8130-3 tracking numbers: W13009-3, W13009-1, W13009-2, W13009-4
7. Link Assy S/N: 2326 was rejected. And replaced by inspected link assy S/N: 2804
 - a. See 8130-3 tracking number H1004-1040
8. Installed both transmission support link assys, P/N: 206-031-589-001 S/N's: RE3985 and 2804 from Aero Products
 - a. See 8130-3 tracking number H1004-1040, W13010.
9. Reinstalled transmission and cowlings
10. Functional flight test required following flight controls disconnected

-----END-----
 Todd Thomas [REDACTED] & P [REDACTED]

4/28/17 1503.4

Performed function test after Maint. Checked OK