

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: New River State: AZ

ZIP: _____ Country: USA

Latitude: 33:55:45 N Longitude: 112:8:26 W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 07/10/2017 Local Time: 0750-0755
mm/dd/yyyy

Time Zone: MST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N273DB

Manufacturer: Charles J. Norris

Model: Lightning

Serial Number: 171

Year of Manufacture: 2016

Amateur-Built: ☒ Yes ☐ No If Yes: ☒ Kit/Plans ☐ Original Design Make: Arion Lightning

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 1320 lbs

Weight at Time of Accident/Incident: 1247 lbs

Number of Seats: 2 Flight Crew Seats: 2

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☒ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Jabiru	3300	33A-2708	11/20/2014	120	63	7.5	
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 05/29/2017
mm/dd/yyyy

Airframe Total Time: 63 hrs

hours measured at (Select one)

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Sensenich

Model: 2A01

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: Ameri-King

Model or Part No.: AK-451

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☒ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☒ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☒ Electronic Multifunction Display
☒ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☐ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Charles J. NorrisCity: PhoenixFractional Ownership Aircraft: ☐ Yes ☒ NoState: AZ ZIP: 85004Country: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**

Airport Name: _____

Distance From Airport Center: _____ sm

Airport Identifier: _____

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A

Airport Elevation: _____ ft. msl

Runway Information

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Charles City of Residence: Phoenix
 Middle Initial: J State: AZ ZIP: 85004
 Last Name: Norris Country: USA
 Age at time of Accident/Incident: 65 Date of Birth: 1951 mm/dd/yyyy
 Certificate Number:

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☒ 3-point</td> <td>☒ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☒ 3-point	☒ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☒ 3-point	☒ 3-point																
☐ 4-point	☐ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☒ Sport ☐ Flight Engineer																	

Principal Occupation ☐ Pilot ☒ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☒ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☒ N/A ☐ Special Issuance	Date of Last Medical <u>05/19/2010</u> mm/dd/yyyy
---	---	---	--

Medical Certificate Limitations

Must wear corrective lenses for distant vision

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>11/18/2016</u> mm/dd/yyyy	Flight Review Aircraft Make: <u>Charles J Norris</u> Model: <u>Arion Lightning</u>
---	---

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Instrument Airplane ☐ Airplane Single-Engine ☐ Instrument Helicopter ☐ Airplane Multi-Engine ☐ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
---	---	--	--

Type Ratings Complex SEL UAV Operating under Light Sport rules.	Student Endorsements (Include dates)
---	---

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1,201	60	1,201		110	221				
Pilot in Command (PIC)		60			110	221				
Time as Instructor										
This Make/Model										
Last 90 Days	46	13	46		0	0				
Last 30 Days	23	5	23		0	0				
Last 24 Hours	0	0	0							

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown				
Available	Used																				
☐ None	☐ None																				
☐ Lap only	☐ Lap only																				
☐ 3-point	☐ 3-point																				
☐ 4-point	☐ 4-point																				
☐ 5-point	☐ 5-point																				
☐ Unknown	☐ Unknown																				
Pilot Certificate(s) <i>(Check all that apply)</i> <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Flight Instructor</td> <td>☐ Commercial</td> <td>☐ US Military</td> </tr> <tr> <td>☐ Private</td> <td>☐ Recreational</td> <td>☐ Airline Transport</td> <td>☐ Foreign</td> </tr> <tr> <td>☐ Student</td> <td>☐ Sport</td> <td>☐ Flight Engineer</td> <td></td> </tr> </table>		☐ None	☐ Flight Instructor	☐ Commercial	☐ US Military	☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign	☐ Student	☐ Sport	☐ Flight Engineer		Medical Certificate <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Class 3</td> </tr> <tr> <td>☐ Class 1</td> <td>☐ Driver's License (Sport Pilot only)</td> </tr> <tr> <td>☐ Class 2</td> <td>☐ Unknown</td> </tr> </table>		☐ None	☐ Class 3	☐ Class 1	☐ Driver's License (Sport Pilot only)	☐ Class 2	☐ Unknown
☐ None	☐ Flight Instructor	☐ Commercial	☐ US Military																		
☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign																		
☐ Student	☐ Sport	☐ Flight Engineer																			
☐ None	☐ Class 3																				
☐ Class 1	☐ Driver's License (Sport Pilot only)																				
☐ Class 2	☐ Unknown																				
Principal Occupation ☐ Pilot ☐ Other ☐ Unknown	Medical Certificate Validity <table style="width: 100%;"> <tr> <td>☐ Without limitations/waivers</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ With limitations/waivers</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Special Issuance</td> <td></td> </tr> </table>		☐ Without limitations/waivers	☐ Unknown	☐ With limitations/waivers	☐ N/A	☐ Special Issuance		Date of Last Medical _____ mm/dd/yyyy												
☐ Without limitations/waivers	☐ Unknown																				
☐ With limitations/waivers	☐ N/A																				
☐ Special Issuance																					

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: _____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
Model: _____

Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> <table style="width: 100%;"> <tr> <td> ☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift </td> <td> ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport </td> </tr> </table>	☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift	☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift	☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport				

Type Ratings

Student Endorsements *(Include dates)*

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KGEU</u> City: <u>Glendale</u> State: <u>AZ</u> Country: <u>USA</u>	Time of Departure Time: <u>0730</u> Time Zone: <u>MST</u>	Destination Airport ID: <u>KGEU</u> City: <u>Glendale</u> State: <u>AZ</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)				
☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)			Altitude of In-Flight Occurrence: <u>5980</u> ft msl
☐ Class A	☒ Class G	☐ Military Operations Area (MOA)	☐ Special
☐ Class B	☐ Demo Area	☐ Airport Advisory Area	☐ Air Traffic Control Area
☐ Class C	☐ Warning Area	☐ Jet Training Area	☐ Unknown
☐ Class D	☐ Prohibited Area	☐ TRSA	
☐ Class E	☐ Restricted Area	☐ FAR 93	

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information (Check all that apply)	Weather Observation Facility
☒ National Weather Service ☐ Flight Service Station ☐ TV/Radio ☒ Automated Report ☐ Commercial Weather Service (DUATS) ☐ On-Board Weather	Facility ID: _____ Observation Time: _____ Time Zone: _____ Distance from Accident Site: _____ nm Direction from Accident Site: _____ degrees true
☐ Company ☐ Military ☐ Internet ☐ None ☐ Unknown	

Basic Conditions ☒ VMC ☐ IMC ☐ Unknown	Light Condition ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown ☒ Day ☐ Night ☐ Bright Night
---	---

Sky/Lowest Cloud Condition ☐ Clear ☐ Thin Broken ☒ Few ☐ Thin Overcast ☐ Partial Obscuration ☐ Unknown ☐ Scattered	Ceiling ☒ None (Clear) ☐ Obscured ☐ Broken ☐ Indefinite ☐ Overcast ☐ Unknown	Temperature: _____ (C) or _____ (F) Dew Point: _____ (C) or _____ (F) Altimeter Setting: <u>29.89</u> in. Hg or _____ MB
Lowest Cloud Condition Height _____ ft agl	Ceiling Height _____ ft agl	

Wind Direction ☒ Variable -or- Direction: _____ degrees true	Wind Speed ☐ Calm ☒ Light and Variable -or- Speed: _____ kts	Wind Gusts ☒ Not Gusting -or- Speed: _____ kts	Visibility <u>>10</u> miles RVR: _____ feet RVV: _____ miles Density Altitude: _____ ft
--	--	--	---

Intensity of Precipitation ☐ Light ☐ Moderate ☐ Heavy ☐ N/A ☐ Unknown	Type of Precipitation (Check all that apply)	Restriction to Visibility (Check all that apply)
	☒ None ☐ Drizzle ☐ Freezing Rain ☐ Rain ☐ Ice Pellets ☐ Snow Shower ☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower ☐ Hail ☐ Snow Grains ☐ Freezing Drizzle ☐ Rain Showers ☐ Ice Crystals	☒ None ☐ Fog ☐ Blowing Dust ☐ Ground Fog ☐ Blowing Sand ☐ Haze ☐ Blowing Snow ☐ Ice Fog ☐ Blowing Spray ☐ Smoke ☐ Dust ☐ Unknown

Icing Forecast	Icing Actual	Turbulence																																						
<table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		<table border="0"> <tr> <th>Amount</th> <th>Type</th> </tr> <tr> <td>☒ None</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Trace</td> <td>☐ Rime</td> </tr> <tr> <td>☐ Light</td> <td>☐ Clear</td> </tr> <tr> <td>☐ Moderate</td> <td>☐ Mixed</td> </tr> <tr> <td>☐ Severe</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ Unknown</td> <td></td> </tr> </table>	Amount	Type	☒ None	☐ N/A	☐ Trace	☐ Rime	☐ Light	☐ Clear	☐ Moderate	☐ Mixed	☐ Severe	☐ Unknown	☐ Unknown		<table border="0"> <tr> <th>Type (Check all that apply)</th> <th>Severity</th> </tr> <tr> <td>☒ None</td> <td>☐ Light</td> </tr> <tr> <td>☐ Clear Air</td> <td>☐ Moderate</td> </tr> <tr> <td>☐ Terrain-Induced</td> <td>☐ Severe</td> </tr> <tr> <td>☐ Convective Turbulence</td> <td>☐ Extreme</td> </tr> </table>	Type (Check all that apply)	Severity	☒ None	☐ Light	☐ Clear Air	☐ Moderate	☐ Terrain-Induced	☐ Severe	☐ Convective Turbulence	☐ Extreme
Amount	Type																																							
☒ None	☐ N/A																																							
☐ Trace	☐ Rime																																							
☐ Light	☐ Clear																																							
☐ Moderate	☐ Mixed																																							
☐ Severe	☐ Unknown																																							
☐ Unknown																																								
Amount	Type																																							
☒ None	☐ N/A																																							
☐ Trace	☐ Rime																																							
☐ Light	☐ Clear																																							
☐ Moderate	☐ Mixed																																							
☐ Severe	☐ Unknown																																							
☐ Unknown																																								
Type (Check all that apply)	Severity																																							
☒ None	☐ Light																																							
☐ Clear Air	☐ Moderate																																							
☐ Terrain-Induced	☐ Severe																																							
☐ Convective Turbulence	☐ Extreme																																							

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

TFR for Prescott area

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft: Wings, flaps, strobes/position lights, landing lights, wiring to/from wings, horizontal stabilizer, vertical stabilizer fuselage in multiple locations, engine prop flange, engine internal TBD, propeller, spinner, canopy partially dislodged (structure intact), engine mount, wing spar box, cowling, landing gear, control service brackets, trim assembly. I believe that the aircraft is not economically repairable.

Property: ~4 foot creosote bush severed at approximately 30 inches, one cactus bush lost 3" off the top, displacement of rocks and dirt at touchdown and slide areas from gear collapse.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Re-cap of July 10, 2017 Flight from KGEU to 33 55' 45" N to 112 8' 26" W

Approximate Departure from KGEU: 0730 MST. Fuel tanks were filled to ~30 gallons that morning before departure.

Tach Start: 62.6

Approximate Emergency Landing Time: 0750 MST

Performed an engine run-up after reaching an adequate oil temperature. CHT, OilP and EGT in normal operating range.

Received clearance to taxi to active runway, 1. Taxied to run-up area and performed a second run-up and moved to the hold line for runway 1. There was traffic in the pattern and I waited for two aircraft landings. The temperature on #3 cylinder reached the warning mark at 350degF, 395Fdeg is the limit. I ascertained that the I would begin the take-off roll and upon reaching 30mph would re-check the CHT. As soon as the plane began rolling for take-off the #3 CHT dropped to 330degF CHT and continued to drop upon rotation and climb-out.

Climb out rpm was at 2660. Propeller pitch had been adjusted on July 7, 2017 to improve cruise speed. At the previous setting max speed was in the 125-130 mph range. I had completed a change in the angle of incidence of the right wing on July 7, 2017 as well. The flight back from Marana area on that day revealed a change in heavy left wing performance to light right wing tendency which was the desired effect on the plane. I had installed a tab on the right aileron at an earlier date and I surmised that its removal would resolve the slight right roll performance. I removed that tab on the morning of July 10. The performance of the airplane during the flight was balanced requiring no pressure in either direction to maintain straight flight.

After reaching 2300 feet, I pulled back the power and leveled off just below 2500 feet msl indicated for the flight to the north. I reset power to 2800 rpm. Between 2800 and 2900 rpm the engine did not feel as if it were operating smoothly. (A defective fuel pump had been replaced at 33.5 hours, January 15, 2017. The engine had previously exhibited rough running symptoms with the previous fuel pump). Airspeed climbed from ~80mph in climb to an indicated 115-120+ mph at this point in the flight

Route of Flight: Northbound from GEU ~360 deg. Remained on a path between KDVT and SATR. Received a TFR warning for continued northbound flight and turned eastbound north of the Phoenix Class B 90/80 section east of Lake Pleasant. Turned NE toward the plateau area in the Mazatzal Wilderness area. I had begun a slow climb from 2500 foot as I passed P48 to the west of my flight path.

Checked to ID TFR which flashed on EFIS while I was changing fuel tanks from left to right tank. I did not visually inspect the tank selection. I conducted the tank change while looking at the instruments and focusing on the turn to the east, and moving my right hand to the EFIS to investigate the TFR warning.

Passing through 5980 feet at an indicated 450fpm climb at 2850rpm the IAS varied between 110-120 mph, I felt a loss of power and the indicated RPM dropped to 1450rpm. I quickly scanned the EFIS and did not see an immediate indication of engine shut down. I leveled off and began a right turn back toward North Phoenix in a south westerly direction.

I moved the throttle cable with no effect on engine RPM. The throttle moved freely. I looked at the engine switch and it was set in the both position. I grabbed the chart in the right seat to ascertain the tower control frequency for KDVT, and made an attempt to contact the tower to advise of my situation. I subsequently reset the transponder while searching for a suitable

Pilot's Complete Narrative from Form 6120

Re-cap of July 10, 2017 Flight from KGEU to 33 55' 45" N to 112 8' 26" W

Approximate Departure from KGEU: 0730 MST. Fuel tanks were filled to ~30 gallons that morning before departure.

Tach Start: 62.6

Approximate Emergency Landing Time: 0750 MST

Performed an engine run-up after reaching an adequate oil temperature. CHT, OilP and EGT in normal operating range.

Received clearance to taxi to active runway, 1. Taxied to run-up area and performed a second run-up and moved to the hold line for runway 1. There was traffic in the pattern and I waited for two aircraft landings. The temperature on #3 cylinder reached the warning mark at 350degF, 395Fdeg is the limit. I ascertained that the I would begin the take-off roll and upon reaching 30mph would re-check the CHT. As soon as the plane began rolling for take-off the #3 CHT dropped to 330degF CHT and continued to drop upon rotation and climb-out.

Climb out rpm was at 2660. Propeller pitch had been adjusted on July 7, 2017 to improve cruise speed. At the previous setting max speed was in the 125-130 mph range. I had completed a change in the angle of incidence of the right wing on July 7, 2017 as well. The flight back from Marana area on that day revealed a change in heavy left wing performance to light right wing tendency which was the desired effect on the plane. I had installed a tab on the right aileron at an earlier date and I surmised that its removal would resolve the slight right roll performance. I removed that tab on the morning of July 10. The performance of the airplane during the flight was balanced requiring no pressure in either direction to maintain straight flight.

After reaching 2300 feet, I pulled back the power and leveled off just below 2500 feet msl indicated for the flight to the north. I reset power to 2800 rpm. Between 2800 and 2900 rpm the engine did not feel as if it were operating smoothly. (A defective fuel pump had been replaced at 33.5 hours, January 15, 2017. The engine had previously exhibited rough running symptoms with the previous fuel pump). Airspeed climbed from ~80mph in climb to an indicated 115-120+ mph at this point in the flight

Route of Flight: Northbound from GEU ~360 deg. Remained on a path between KDVT and SATR. Received a TFR warning for continued northbound flight and turned eastbound north of the Phoenix Class B 90/80 section east of Lake Pleasant. Turned NE toward the plateau area in the Mazatzal Wilderness area. I had begun a slow climb from 2500 foot as I passed P48 to the west of my flight path.

Checked to ID TFR which flashed on EFIS while I was changing fuel tanks from left to right tank. I did not visually inspect the tank selection. I conducted the tank change while looking at the instruments and focusing on the turn to the east, and moving my right hand to the EFIS to investigate the TFR warning.

Passing through 5980 feet at an indicated 450fpm climb at 2850rpm the IAS varied between 110-120 mph, I felt a loss of power and the indicated RPM dropped to 1450rpm. I quickly scanned the EFIS and did not see an immediate indication of engine shut down. I leveled off and began a right turn back toward North Phoenix in a south westerly direction.

Pilot's Complete Narrative from Form 6120

I moved the throttle cable with no effect on engine RPM. The throttle moved freely. I looked at the engine switch and it was set in the both position. I grabbed the chart in the right seat to ascertain the tower control frequency for KDVT and made an attempt to contact the tower to advise of my situation. I subsequently reset the transponder while searching for a suitable landing site. I selected an area to the east of I-17, a plateau north of the town of New River.

I sought a landing site that would offer easier retrieval and the selected area was adjacent to a dirt/gravel road with a clear path to set down the aircraft. I decreased speed to the 80-85mph range to achieve best glide. I attempted to raise KDVT tower again. My indicated RPM slowing dropped from the 1450 to 1000 rpm as I was turning base to final to land on the plateau. I selected a flap setting at 20 degrees on base.

On final I still had excess airspeed, I pulled back on throttle to see if there would be any effect. There was no change in engine RPM at 1000rpm indicated.

I lined up down the approximate centerline N-S on the plateau. As I still had too much airspeed for a touchdown, I proceeded descent over the rim of the plateau. I put in the rest of the flaps to 40 degrees as I approached the edge and reached down to ensure fuel was off for the rough landing. There was a road paralleling my flight line, but it veered off to the SE and I could not see the road down the slope. I elected to land straight ahead rather than risk an unusual attitude for touchdown.

The landing area beyond the rim was typical AZ landscape with small brush, cactus, rock and undulating surface. My left wing tip clipped a small creosote bush as I was flaring for landing. Touchdown was rough and angled slightly east of south, upon hitting an area of depression, the gear collapsed and the propeller struck the ground and sheared off. At this point the aircraft slid on its belly to its resting place on the right side of Coyote Pass Road (heading south).

The time of the emergency landing was ~0750 hours MST.

Upon coming to a rest I shut down all the switches. The ELT remained on, activated by the impact of the gear collapse.

I exited the aircraft, called my wife and indicated that I had an emergency landing and I would give her a call back. I then called Greg Hobbs, the owner of the build center that I had built N273DB the previous year. Greg loaded up his truck and trailer and departed the Marana area to assist in the recovery of the aircraft.

Bill Jordan, a local resident, came up the road from his house in a four wheeler to provide assistance. We began collecting some debris and I pulled out my iPad and located the airport manager number for KDVT. I called him and got the number for the KDVT tower and contacted the tower, spoke to Travis and advised him of the emergency landing. Travis indicated that he would take care of contacting appropriate personnel with the FAA and NTSB. I then looked up the number for the New River area Fire Department. I was not injured from the landing impact, so I chose not to call 911. Upon contacting the fire department, I explained that I had effected an emergency landing, my approximate location and the receptionist indicated that the on-duty Fire Marshall would give me a call.

Bill and I retrieved some of the parts and he brought over two 5 foot sections of 2x6 boards that we used to turn the aircraft to clear the road.

Pilot's Complete Narrative from Form 6120

In the meantime, a Phoenix Police helicopter began searching the area for the wreckage just east of I-17. The pilot was in the air for about 15 minutes prior to working toward my location. The Fire Department arrived with a number of vehicles. The Maricopa county sheriff's department also arrived on the scene with a number of officers. The Phoenix Police helicopter landed as the vehicles were arriving. I spoke briefly with one of the officers on board. At their request I shut down the ELT.

The EMT's from the Fire Department requested they quickly check my vitals. I agreed. BP/Pulse rate were elevated and did come down on the second check. I was ambulatory, alert and declined further medical attention.

Upon discussion with the Fire Department and coordinating with Greg Hobbs, we ascertained that he was coming with necessary equipment to ground the aircraft when we extracted the fuel later and prior to retrieval.

I contacted the insurance company agent and advised them of the incident. They put me in touch with AIG, the underwriter.

The Fire Department personnel left, my wife arrived and I coordinated with the Sheriff's department to leave the scene for approximately 45 minutes to retrieve my pickup truck and some tools and fire extinguishers from my hangar at KGEU.

A sheriff's department deputy remained on-site until we were given the go ahead to remove the airplane in the late afternoon. Other individuals from the Maricopa county Sheriff's office arrived later and indicated they were conducting some training on accident sites.

Steve Stein from the NTSB called me. I recounted the incident. He indicated that the FAA would be sending a team out led by Scott Hutson and I would receive a subsequent call from Mike Heun who would be assigned to the investigation. I was advised by Steve to leave the aircraft in place and to not attempt a recovery. Greg Hobbs had arrived a few minutes earlier with his recovery vehicle.

The FAA team arrived with Scott Hutson and Scott "?". They began their investigation. They marked out the areas where the aircraft touched down, collected parts along the path and took pictures of the aircraft. Scott Hutson asked me questions about the events that led to the emergency landing.

Toward the end of their on-site review, Greg and I removed the cowling to inspect the engine to ascertain the cause of the engine problem. The float bowl was removed and revealed a minimal amount of fuel in the bowl. The fuel line to the carburetor also appeared devoid of fuel. The gascolator sump still had fuel in it. An inspection inside the cockpit revealed that the wing spar box had been bent in the landing and the fuel line from the right tank was kinked. Fuel remained in both filters, with the left filter being nearly full while the right filter was about 1/3 full.

The FAA team spent some time in their vehicle and speaking with the NTSB rep, Steve Stein. Before their departure I was advised that Mike Heun would give me a call. They indicated that we could now recover the aircraft.

In parallel, I had been in contact with AIG, Renee Bertonlina. She reviewed the procedures for recovery and dispensing with the aircraft. Greg Hobbs reviewed the wreckage and ascertained that the airframe,

Pilot's Complete Narrative from Form 6120

wings were not serviceable. The ailerons might be reusable. The metal frames (engine mount, wing spar box) were beyond repair. Status of the engine after the propeller strike is yet to be determined. Given the extent of damage, I elected to go with the AIG recommendation to have their agent, Air Transport, recover the aircraft and move it to their facility. I advised the FAA on-site team and they are familiar with the organization and felt that would make subsequent inspection by the FAA/NTSB more expeditious. Renee sent me the contact information for Air Transport and I contacted them and provided the directions and GPS coordinates to the landing site.

The FAA and sheriff's department deputy departed the area. Greg and I proceeded to remove the fuel from the wings prior to Air Transport's arrival. We confirmed the aircraft was grounded and then used a siphon to remove the fuel from each wing. Approximately 25 gallons of fuel were removed from the wings.

Air Transport arrived at approximately 1600 MST and we proceeded with removing the wings and loading the wings and fuselage onto the recovery trailer. We completed the operation around 1640 MST. I picked up the trash around the area and Mr. Hobbs and I departed. Mr. Jordan had assisted us during the entire day.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

Should have spent less time on communication and more time troubleshooting the engine.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☐ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Unsure of the cause of the engine loss of power.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
(Convert from pounds, as necessary)

30 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**

Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

I opened the canopy, it had shifted to the right and the right guide tab was bent. I stepped out of the aircraft onto the wing per normal exit procedures. It was a short step to the ground from the wing.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for *other* aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

07/11/2017

mm/dd/yyyy

Name of Pilot/Operator: Charles J Norris

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR17LA148

Reviewed by NTSB Regional Office

WPR

Name of Investigator

Michael Huhn

Date Report Received

7/13/17