



RECORD OF CONVERSATION

Joshua D. Cawthra
Senior Aviation Accident Investigator
Western Pacific Region

Date: August 8, 2017
Person Contacted: Niknam Nickraves
NTSB Accident Number: WPR17LA164

Narrative:

During a telephone conversation with Mr. Nickraves, he reported that he was present and doing an oil change along with various other work while the other mechanic was installing the second set of brakes in the airplane. In addition, Mr. Nickraves reported that he checked the airplane for flight control tension, noting that the operation was smooth, and visually looked at the ailerons while he was moving the control yoke. He added that at no time did he noticed that the aileron cables were installed backwards. Mr. Nickraves stated that all work on the airplane was performed in accordance with the Piper Aircraft Maintenance Manual.