



RECORD OF CONVERSATION

Date: July 12, 2018

Time: 1005 - 1010

Person Contacted: Davis Lille (certified flight instructor)

Subject: WPR17LA175

On July 11, 2018, the right seat passenger, Chandler Riesterer, in an email to the NTSB IIC, stated that a few days prior to the accident the pilot, Brody Burnell, was telling people and his flight instructor, David [Lille], that he was having trouble with the fuel selector.

On July 12, 2018, in a follow-up telephone interview with Mr. Lille, the IIC asked Mr. Lille if the pilot, Brody Burnell, had ever mentioned during any of their conversations that there was a problem with the airplane's fuel selector? Mr. Lille replied that Mr. Burnell never mentioned anything about the fuel selector being an issue during any of their conversations.

Thomas M. Little
Senior Aircraft Accident Investigator
National Transportation Safety Board
Western Pacific Region
Federal Way, Washington