



Photo 1 – View of Lower Left Hand Varicam (Courtesy of Neptune Aviation)



Photo 2 – Left Hand Varicam Drive Stop Coupling and Yoke (Courtesy of Neptune Aviation)



Photo 3 – Left Hand Varicam Drive Stop Coupling and AN174H7A Bolt (Courtesy of Neptune Aviation)



Photo 4 – Missing Left Hand Varicam Drive Stop Coupling AN174H7A Bolt (Courtesy of Neptune Aviation)