



SUMMARY OF FINDINGS

Tealeye Cornejo
Air Safety Investigator (Field)
Western Pacific Region

Date: September 2017
Person Contacted: Charles Wright FAA inspector Portland FSDO
NTSB Accident Number: WPR17LA194

Narrative:

During a discussion with inspector Wright, he reported that he and the pilot examined the airplane logbooks, airplane, and engine. They did not find anything mechanically wrong with the airplane. He also photographed the engine and took a fuel sample. However, the pictures and findings of the fuel sample were not made available to the investigation.