



MEMORANDUM FOR RECORD

Stephen Stein
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety – Western Pacific Region

Weather Report – Camarillo Airport (CMA), Camarillo, California
Date & Time: September 4, 2017 1358 PDT
NTSB Accident Number: WPR17LA197

CMA is a nearby weather observation facility located about 8 nm south of the accident site.

METAR/SPECI from KCMA, Camarillo, Camarillo Airport (United States) .		
SA	05/09/2017 03:55->	METAR KCMA 050355Z AUTO 24005KT 9SM OVC018 23/20 A2992 RMK AO2 SLP140 T02280200=
SA	05/09/2017 02:55->	METAR KCMA 050255Z 23007KT 9SM FEW012 BKN023 23/19 A2991 RMK AO2 SLP137 T02330194 53008=
SA	05/09/2017 01:55->	METAR KCMA 050155Z 23011KT 9SM BKN023 24/20 A2990 RMK AO2 SLP133 T02390200=
SA	05/09/2017 00:55->	METAR KCMA 050055Z 21011KT 10SM FEW018 25/19 A2989 RMK AO2 SLP130 T02500194=
SA	04/09/2017 23:55->	METAR KCMA 042355Z 22007KT 10SM SCT020 27/19 A2989 RMK AO2 SLP129 T02670194 10272 20256 56010=
SP	04/09/2017 23:16->	SPECI KCMA 042316Z 22011KT 10SM FEW020 27/20 A2990 RMK AO2 T02670200=
SA	04/09/2017 22:55->	METAR KCMA 042255Z 25008KT 9SM BKN020 26/20 A2990 RMK AO2 SLP132 T02610200=
SA	04/09/2017 21:55->	METAR KCMA 042155Z 22011KT 9SM OVC022 26/20 A2991 RMK AO2 SLP135 T02610200=
SA	04/09/2017 20:55->	METAR KCMA 042055Z 20011KT 10SM OVC023 26/19 A2992 RMK AO2 SLP139 T02610194 58004=
SA	04/09/2017 19:55->	METAR KCMA 041955Z 20014KT 10SM OVC021 26/19 A2993 RMK AO2 SLP140 T02610194=
SP	04/09/2017 19:18->	SPECI KCMA 041918Z 20015KT 10SM BKN019 27/21 A2993 RMK AO2

T02670206=