



Photo 1 –N32064 Post accident photo of airplane in field




Photo 2 – Substantial damage at the fuselage to landing gear attachment



Photo 3 – Landing Strip