

...ations
umber of
entries.)

9.9

sted as
time

umber:

YEAR 20 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
--------------------	---------------------------	-------------------	-----------------------------	---

MAKE: Cessna
MODEL: 172m
S/N: 17263145
REG. NO: N4395R
WORK ORDER: 134



CB Aviation, Inc.
[Redacted]
Ogden, UT 84405 USA
Phone: [Redacted]

DATE: 11/24/2017
AVC TSN: 0
TACH: 1580.5

Airframe Entries

- (1) AIRFRAME HAS BEEN INSPECTED FOR AN ANNUAL HOUR INSPECTION IN ACCORDANCE WITH THE SCOPE AND DETAIL OF APPENDIX D PART 43 AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED AT THIS DATE AND TIME
- (4) ELT OPERATIONAL CHECKED SATISFACTORY PER FAR 91.207d. BATTERY EXPIRATION DATE NOV. 2019
- (5) AD RESEARCH C/W USING ATP REVISION
- (6) AD2011-10-09 TO PREVENT SEAT SLIPPAGE OR THE SEAT ROLLER HOUSING FROM DEPARTING THE SEAT RAIL INSPECTION C/W BY VISUAL INSPECTION, FOUND TO BE ACCEPTICAL. NEXT DUE TACH 1590.5 OR NOV/2018
- (8) POWERFLOW SYSTEMS ICA C/W PER INSTALLATION INSTRUCTIONS AND INSTRUCTIONS FOR CONTINUED AIRWORTHINESS PFS-13250-00 REV G FOUND TO BE ACCEPTICAL. NEXT DUE TACH 1680.5 OR NOV/2018
- (10) LOWER COWLING DZUS FASTENER REPLACED WITH NEW DZUS P/N S1115-32
- (11) UPPER COWLING MOUNT REPLACED WITH NEW MOUNT P/N J-74444-42
- (12) VACUUM REGULATOR FILTER P/N B3-5-1 REMOVED. INSTALLED NEW VACUUM REGULATOR FILTER P/N B3-5-1
- (14) REPAIRED DAMAGED WIRING AND SECURED TO THE ENGINE BAFFLING WITH AN ADEL CLAMP P/N MS21919WDG7
- (15) OIL COOLER HOSE REMOVED. INSTALLED NEW MIL-H-6000 #6 HOSE AND FIRESLEEVE WITH EXISTING FITTINGS
- (17) #4 PRIMER LINE REPOSITIONED AND SECURED
- (18) LOWER ENGINE MOUNTS P/N J9613-49 REMOVED. INSTALLED NEW LOWER ENGINE MOUNTS P/N J9613-49 TORQUE BOLTS AT 450 IN/LB
- (21) NOSE STRUT SCISSOR BOLTS RESECURED
- (24) INDUCTION FILTER P/N BA-4108 REMOVED. INSTALLED NEW INDUCTION FILTER P/N BA-4108
- (25) CONCOR TIRE P/N 072-314-0 S/N 9041W00180 REMOVED. INSTALLED NEW AIR HAWK TIRE P/N 06-07900 S/N B3E43117. REPACKED BEARINGS. SERVICED 29 PSI AIR. LEAK CHECK GOOD.
- (26) AIR TRACK TIRE P/N 30620 S/N A1E43313 REMOVED. INSTALLED NEW AIR HAWK TIRE P/N 06-07900 S/N B3E43117. REPACKED BEARINGS. SERVICED 29 PSI AIR. LEAK CHECK GOOD.
- (29) RIGHT FUEL VENT HOSE REPLACED WITH NEW HOSE
- (30) REINSTALLED DOOR HANDLE LOOSE SPRING. OPERATIONAL CHECK GOOD.
- (31) LEFT FUEL CAP LANYARD REPLACED WITH NEW LANYARD P/N C100085-3

I certify the work performed as described herein was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and is approved for return to service in respect to that work performed

DATE: 11/24/2017

SIGNED: [Redacted]

APR

Work Order: 134

01.14.2018 20:56