


MAKE: Cessna
MODEL: 182i
S/N: 18280965
REG. NO: N3525T
WORK ORDER: 6S50351



Choice Aviation, LLC

Hamilton, MT Shop - 6S5
516 Airport Rd
Hamilton, MT 59840

DATE: 10/26/2017
A/C TSN: 1325.5
TACH: 1325.5

Airframe Entries

Removed this date Bendix King KT76C Transponder P/N 066-01156-0101 S/N 11925.

Installed L-3 Communications NGT-9000 Multilink Surveillance System P/N 9029000-20000 S/N LXE11408, PIM-9000 PED Interface Module P/N 9230-17005-01 S/N 00002390, RAMI AV-801 GPS Antenna S/N 170319, L-3 Communications NY-164 Directional Antenna P/N 805-10890-001 S/N 88954, L-3 Communications L-3 A5 Configuration Module P/N 9230-17003-01 S/N 02621.

Installation was performed under STC SA02444AK Dated March 31, 2015. System was installed I.A.W. L-3 Aviation Products Lynx NGT-9000 Multilink Surveillance System Installation Manual 0040-17001-01 Revision M July 13 2017.

See FAA Form 337 dated this date for additional information. Weight & Balance and equipment list have been updated....Installed this date True Blue Power TA102 USB Charging Port S/N E17-12382. Installed I.A.W. True Blue Power Installation Manual 9017942 Revision J January 4, 2017 W&B Negligible....Tested #2 Glideslope System with IFR 4000 test set. System was tested in several ILS frequency's all tests passed. #2 system was compared to #1 system for sensitivity both systems flagged with-in 1 db of each other....I certify the altimeter system, altitude reporting equipment, and static system tests and inspections as required by FAR 91.411 have been performed and the systems have been found to comply with appendix E of part 43....I certify that the transponder was tested as required by FAR 91.413 and was found to comply with appendix F of part 43.

Model: NGT-9000 S/N: LXE-11408

DATE: 10/26/2017


SIGNED:

Work Order: 6S50351

Thomas Reed, A&P: [REDACTED]

Printed by EBis 3 (datcomedia.com)

ENGINE MODEL:
ENGINE S/N:
REG. NO: N3525T
WORK ORDER: 6S50351



Choice Aviation, LLC

Hamilton, MT Shop - 6S5
516 Airport Rd
Hamilton, MT 59840

DATE: 10/26/2017
A/C TSN: 1325.5

TACH: 1325.5

Engine Entries

Changed oil and filter (9qts Aeroshell 15w-50). Run up and leak check good.

DATE: 10/26/2017

SIGNED:

Work Order: 6S50351

Michael Ellis, A&P: [REDACTED]

Printed by EBis 3 (datcomedia.com)

MAKE: Cessna
MODEL: 182t
S/N: 18280965
REG. NO: N3525T
WORK ORDER: 6S50449



Choice Aviation, LLC

Hamilton, MT Shop - 6S5
516 Airport Rd
Hamilton, MT 59840

DATE: 12/5/2017
A/C TSN: 1334
TACH: 1334

Airframe Entries

Remove and disassemble Nose Wheel/Tire assembly. Inspect inner tube for damage, found crack in tube sidewall. Installed new 5:00 x 5 inner tube and reassemble Wheel/Tire. Reinstall Wheel/Tire assembly....Replaced Velcro on Baggage Close out Panel.

DATE: 12/5/2017

SIGNED:

Work Order: 6S50449

Herman Hill, A&P: [REDACTED]

Printed by EBis 3 (datcomedia.com)