

N707DF

ENGINE LOG BOOK



Service Information

Consult the Continental Motors web site at continentalmotors.aero for engine related news or announcements. Continental Motors Internet Service contains useful information for Continental Motors engine owners, including electronic versions of the most current engine Instructions for Continued Airworthiness and service documents that may be pertinent to your engine model.

If Internet access is not available, contact our Customer Service Department at:
1-888-826-5465 Toll free in the United States or
1-251-436-8299 International

Engine Returns

Return engines for core credit with this log book to:

Continental Motors, Inc.
2039 Broad Street
Mobile, AL 36615 USA

Return engines for overhaul with this log book to:

Continental Motors, Inc.
Factory Service Center
8600 County Road 32
Fairhope, Alabama 36532 USA

**USE ONLY FUEL SPECIFIED IN OPERATOR'S
MANUAL OR TYPE CERTIFICATE DATA SHEET
USE OF AUTOMOTIVE FUEL IS PROHIBITED**



Continental Motors

FAA PRODUCTION CERTIFICATE NO. 508

Printed:09/13/2017

Test Date09/12/2017

This engine model TSI0550K1B, serial number 1034629 was manufactured by Continental Motors, Inc. in accordance with approved design data and the applicable requirements of 14 CFR, Part 21. The approved design data for this engine incorporates all changes required by applicable FAA Airworthiness Directives and Continental Motors Service Bulletins.


CONTINENTAL MOTORS, INC.

d
—
1d
s,

S/N: 1034629
S/N: 1621
Flight Hour Meter: 51.9 Hrs

- Maintenance performed:
- Changed oil and filter. Serviced system with 8qts Aeroshell 100W Plus oil and installed new CH48108-1 oil filter. Performed ground run, leak checks good. Reinstalled engine cowl.
 - Oil sample taken and sent for analysis.
 - Cut open old oil filter and checked for metal contamination, none found at this time.
 - Complied with SA 13-01. exhaust crack inspection. no defects noted.
 - Complied with turbo check valve inspection. no defects noted and leak checks good.

I certify that with respect to the work performed this engine was repaired and inspected in accordance with current FAA regulations. Only those items specified in the work order have been inspected and found to be airworthy and returned to service. Pertinent details of this repair are on file at this agency under Work Order No. PA-18-08229.

Authorized Representative

[illegible]