



## Memorandum for Record

Tealeye Cornejo  
Air Safety Investigator  
National Transportation Safety Board  
Investigator in Charge

---

NTSB Accident Number: WPR18FA261  
Aircraft Registration & Make/Model: N382T / Gruber Beelzabub  
Accident Location: Rochester, Washington  
Accident Date: September 14, 2018

---

### Flying Pilot

The Thurston County Coroner's Office in Tumwater, Washington performed the pilot's autopsy. His cause of death was listed as blunt force trauma of the head.

### Pilot-rated passenger

The Thurston County Coroner's Office in Tumwater, Washington performed the pilot's autopsy. His cause of death was listed as blunt force trauma of the head.

Toxicology testing for the pilot-rated passenger was performed by the Federal Aviation Administration Forensic Sciences Laboratory in Oklahoma City, Oklahoma. There were no volatiles detected; carbon monoxide and cyanide testing were not performed. The toxicology test yielded the following positive results for tested drugs 0.045 (ug/mL, ug/g) morphine detected in urine, but not in the blood cavity.