

AIRCRAFT LOG

REMARKS

VOR Receiver operation checked
in accordance with FAR 91.25

DATE

Enter here general data with reference to "Line" and "Periodic" inspections - Rigging Changes - Alterations - Repairs - Service Letters - and changes in propeller or engine - as outlined in the front of this book, under the heading, "INSTRUCTIONS FOR USE OF THIS LOG BOOK." ALL DATA must bear the endorsement of a certificated mechanic, and his rating and certificate number must be shown.

Date Bearing error Place Signature
VOR 1 VOR 2

19

4/1/06 I certify that this Aircraft has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

2-1-15 ACA 4863.2 C/W AD 80-11-04 TUL N.P.'S, 11-10-09 SAMS + RALS, 09-10-09 R2
BY INST. PLACED, REPL. HORIZ STAS WITH 3 SERVICEABLE UNIT. REPL. LT M/G TIRE + TUBE,
N/G TIRE AND TUBE, REPACK ALL WHEEL BOLS, REBAL CLIPOLS, REPL. BRAKE BOLCS
RA 164-30175, REPL. LT. M/G BRAKE LINK AT STRUT, SERVICED BRAKES WITH MIL-IT-5606.
REPL. 627 IN TT. 13P-1015, REP 9-16. ELT 7077 + INP. C/W PER FAR 91.207d NO DEFECTS. REPL.
REPL. HORIZ GAS COUPLER TO CARB, REPL. CHRYSLER PLUUGER ASSY MC 0756010-11, REPL. STERNING
RWD DOORS PLW MC 0913304-3, REPL. M/G STAN CUFFS + WING STRUT CUFFS, REPL. BLEN + STAS
TOPS PIN SA 0930004-10, -11. REPL. RA 4108 AIR FICOL, RC-25 BATTERY, FUEL CAP CASKTS,
INST. AIRBOX CARPET KIT. MX-300 REPAIRED. I CERTIFY THIS AIRCRAFT WAS FOUND INP.
I AM AN AWWUL WSP. + DETERMINED TO BE IN AIRWORTHY CONDITION THIS DATE.

AIRCRAFT LOG

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE

ELT
adde
I cer
14 C

SIGNATURE OF
PILOT

AIRCRAFT LOG

VOR Receiver operation checked in accordance with FAR 91.25			DATE	REMARKS
Date	Bearing error	Place	Signature	

5/2/2017 N6627G Tach time 2984.0

Removed and discarded old cracked trim panels on the lower switch area below the instrument panel. Removed and discarded all old fuse holders.

Installed new PMA stationary plastic panel and switch panel trim pieces part # K0413467-5 and UK0413462-22 manufactured by Plane Plastic Inc.

Installed all new PMA Klixon 2TC4 circuit breakers into the breaker panel matching the wire size and load.

Jonathan Smalldridge

Cessna 150L ser#: 15072127 N6627G Tach: 2984.1 and TTIS: 4980.6 05-03-2017

Continental O-200-A ser#: 253565-A-48 Tach: 2984.1 TSMOH: 577.6

McCauley 1A101 MCM 69-48 ser#: 66370 Tach: 2984.1 and TTIS: 4980.6

ELT complies with FAR 91.207 (d)- battery dated 12-18. A/D notes thru 2017-08 researched see attached in addendum.

I certify that this aircraft has been inspected in accordance with an Annual Inspection Procedure per Title 14 CFR part 43 appendix D and was determined to be in an airworthy condition.

Leon

MEMORANDA

[illegible]

TRANSPONDER CERTIFICATE
THIS TRANSPONDER WAS TESTED AS
FOUND TO BE WITHIN THE LIMITS SP

DATE 2/5/2016

TYPE A-150 INSP

FLIGHT CON

CERTIFIED REPA

5550 N AIRPORT RD

MILTON AIRPORT 2R4 TRANSP

TRANSPONDER CERTIFICATION LOGBOOK ENTRY
THIS TRANSPONDER WAS TESTED AS REQUIRED BY FAR PART 91.413a AND
FOUND TO BE WITHIN THE LIMITS SPECIFIED IN FAR PART 43 APPENDIX F.

TYPE A+150 INSPECTOR [REDACTED]

FLIGHT CONTROL SERVICES
CERTIFIED REPAIR STATION #0FHR414L
5550 N AIRPORT RD, MILTON FLORIDA 32583
FLIGHTCONTROLREPAIR.COM

5550 N AIRPORT RD, MILTON, MA 02186 (850) 665-2150
MILTON AIRPORT 2R4 TRANSPONDERREPAIR.COM
Overhauled by

FE
67211

CERTIFICATION
Certified Repair Station NO. 322-6
9294

Ser. No. 522

Mfg. EK

Insp. By .

Repairman

out Below

FOR FURTHER SERVICE

THIS UNIT TESTED AND APPROVED _____ Date _____

TESTED BY: KELLEY INSTRUMENTS, INC. DATE
1024 S. SANTA FE
WICHITA, KANSAS 67211
FAA C.R.S. 322-6

SERVICEABLE

08/05/2017. Tach time 3005.8

Removed original starter motor. Installed new FAA-PMA starter C12ST2 starter by Skytec.
W&B updated.

Date

Removed original starter contactor S1991-1. Installed new equivalent contactor 7-1037
by Accurate Parts Company.

Signature

12/09/2017 N6627G Tach: 3025.9

Removed Mitchel MX300 Nav/Com radio with tray, wiring and CDI indicator.

Removed Sigtronics SP-400 intercom and wiring.

Manufactured new wiring harness.

Installed iCom IC-A210 Com radio. Tested radio communications and intercom functions.

Installed Narco NAV-122 VOR/LOC/MB. Checked Nav performance within specs.

Updated the A/C W&B. *APPROVED FOR RETURN TO SERVICE*

Signature

2017

*11/12/17 Inst
Tach. 3022.9*