

From: [REDACTED]
To: [REDACTED]
Subject: N669WH accident
Date: Tuesday, March 6, 2018 12:23:36 PM

Tealeye,

I just examined the aircraft involved in the landing incident yesterday. They had moved it from the accident site to their hangar in Bountiful Utah. The left wing was folded in the middle, which occurred after the aircraft flipped onto its top. The rudder was also bent up from the over turn of the aircraft. Both have sustained damage to constituent an accident in my opinion. The owner is going to forward both us pictures which he took at the scene. I have a couple pictures if you would like to see them as well. Let me know how we want to proceed. Thanks

Jon

Jon A. Hanson

Principal Avionics Inspector
Salt Lake City-Flight Standards District Office

