



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR18LA164
Aircraft Registration & Make/Model: N518Z / Bell 206B
Accident Location: Sander, KY.
Accident Date: June 5, 2018

Brent Spry
Airport manager, Madison Municipal Airport
February 3, 2021

In a telephone interview with Mr. Spry, he stated that he was working on the day of the accident but was not present when the helicopter was fueled. He stated that his records show the pilot purchased 67.86 gallons of Jet A from the self-pump station on the airport. The pilot fueled the helicopter himself. Mr. Spry stated that after hearing of the accident, he shut down the Jet A pump and alerted the Quality Assurance contact for Eastern Aviation Fuel, who tested the pump using their checklist. He stated the results were negative. Mr. Spry also stated that no one complained about the Jet A fuel before or after the accident.