

From:

Subject:

Date:

RE: Airspeed Indicator question (WPR18LA179)

Wednesday, July 11, 2018 9:37:12 AM

Mr. Huhn,

Please find my responses to your questions below.

V/r,

Ned R. Piccinini

From: Huhn Michael [mailto:]

Sent: Tuesday, July 10, 2018 8:15 PM

To: Ned Picininni []

Subject: Airspeed Indicator question (WPR18LA179)

Hi Ned

In your responses you cited the airspeed only went to 43 kts and was "fluttering"

I took that to mean you were getting the values from the circular/analog ASI gauge just to the right of the Garmin screens , but I don't want to assume anything

- I verified that both the Garmin G-500 and the circular/analog ASI gauge were reading similarly.
1. Can you confirm that's where you were looking for your airspeed info?
 - As noted above I checked both instruments to confirm airspeed indication.
 2. I understand the airplane is equipped with a G-500 or G-600-
 - a. Do you recall which equipment it is
 - G-500
 - b. Do you recall whether it displays airspeed?
 - Yes
 - c. If so, do you recall whether you looked at that, and if so, what value(s) it was displaying?
 - 43 kts fluttering

thanks

Michael Huhn
Air Safety Investigator
NTSB Western Pacific Region
[]