



Photo 1 – N5682B showing right wing damage



Photo 2 – N5682B showing damage to landing gear



Photo 3 – Right main landing gear of N5682B



Photo 4 – Three vehicles struck by N5682B



Photo 5 – Car struck by N5682B



Photo 6 – SUV struck by N5682B



Photo 7 – Truck struck by N5682B