



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Western Pacific Region

Date: February 3, 2021
Person Contacted: Mr. Bud Umfress (Operator)
NTSB Accident Number: WPR18LA189

Narrative:

During a telephone conversation with Mr. Umfress, he reported the airplane's engine was sent to Tulsa Aircraft Services to be repaired and overhauled. During the overhaul there were no anomalies noted that would have precluded normal operations. After overhaul the engine was installed onto another airframe and has been flying ever since.

END.

Submitted by: Samantha Link