



RECORD OF CONVERSATION

All persons listed were interviewed by Zoë Keliher

The following is a summary of conversation:

MATTHEW BATES (OWNER)

Mr. Bates was the student's certified flight instructor was the owner of the airplane. He stated that he and the student had never flown together in hotter temperatures because he thought the airplane wouldn't have the performance to takeoff. He had taught the student that while on final approach, the mixture control was to be set to a full rich position and the carburetor heat should be on. He thought that this may have contributed to the loss of engine power.

Zoë Keliher
Air Safety Investigator
Western Pacific Region