



MEMORANDUM FOR RECORD

Stephen Stein
Air Safety Investigator
National Transportation Safety Board
Office of Aviation Safety – Western Pacific Region

Weather Report – Mid-Carolina Regional Airport (RUQ), Salisbury, North Carolina
Accident Date & Time: June 29, 2018; 1600 EDT
NTSB Accident Number: WPR18LA194

RUQ is a nearby weather observation facility located about 3 nm southwest of the accident site.

METAR/SPECI from KRUQ, Salisbury, Rowan County Airport (United States) .		
SA	29/06/2018 23:55->	METAR KRUQ 292355Z AUTO 03004KT 10SM CLR 28/21 A3003 RMK AO2 T02810207 10328 20281=
SA	29/06/2018 23:35->	METAR KRUQ 292335Z AUTO 03007KT 10SM SCT050 SCT070 28/21 A3003 RMK AO2 T02820206=
SA	29/06/2018 23:15->	METAR KRUQ 292315Z AUTO 02008KT 10SM BKN060 BKN070 OVC085 29/21 A3003 RMK AO2 T02900208=
SA	29/06/2018 22:55->	METAR KRUQ 292255Z AUTO 04012G15KT 10SM BKN060 BKN070 BKN085 31/21 A3002 RMK AO2 T03090209=
SA	29/06/2018 22:35->	METAR KRUQ 292235Z AUTO 01004KT 10SM CLR 31/20 A3001 RMK AO2 T03110203=
SA	29/06/2018 22:15->	METAR KRUQ 292215Z AUTO 01004KT 10SM SCT055 32/20 A3001 RMK AO2 T03170202=
SA	29/06/2018 21:55->	METAR KRUQ 292155Z AUTO 02007KT 10SM SCT055 32/20 A3002 RMK AO2 T03220203=
SA	29/06/2018 21:35->	METAR KRUQ 292135Z AUTO 04003KT 10SM SCT060 32/20 A3002 RMK AO2 T03190201=
SA	29/06/2018 21:15->	METAR KRUQ 292115Z AUTO 00000KT 10SM SCT060 BKN070 31/20 A3002 RMK AO2 T03110204=
SA	29/06/2018 20:55->	METAR KRUQ 292055Z AUTO 04007KT 10SM SCT060 SCT070 BKN080 33/20 A3002 RMK AO2 T03260201=
SA	29/06/2018 20:35->	METAR KRUQ 292035Z AUTO 03005KT 10SM BKN060 BKN080 32/20 A3002 RMK AO2 T03190197=

SA	29/06/2018 20:15->	METAR KRUQ 292015Z AUTO 00000KT 10SM SCT060 BKN070 32/19 A3002 RMK AO2 T03170190=
SA	29/06/2018 19:55->	METAR KRUQ 291955Z AUTO 02004KT 10SM BKN060 BKN070 32/20 A3002 RMK AO2 T03220200=
SA	29/06/2018 19:35->	METAR KRUQ 291935Z AUTO 00000KT 10SM SCT060 32/19 A3002 RMK AO2 T03230191=
SA	29/06/2018 19:15->	METAR KRUQ 291915Z AUTO 00000KT 10SM SCT060 32/19 A3002 RMK AO2 T03230192=
SA	29/06/2018 18:55->	METAR KRUQ 291855Z AUTO 00000KT 10SM CLR 32/19 A3003 RMK AO2 T03200187=
SA	29/06/2018 18:35->	METAR KRUQ 291835Z AUTO 04003KT 10SM SCT055 32/20 A3003 RMK AO2 T03180199=
SA	29/06/2018 18:15->	METAR KRUQ 291815Z AUTO 00000KT 10SM OVC049 32/20 A3004 RMK AO2 T03200198=
SA	29/06/2018 17:55->	METAR KRUQ 291755Z AUTO 00000KT 10SM SCT049 32/20 A3004 RMK AO2 T03160201 10316 20226=
SA	29/06/2018 17:35->	METAR KRUQ 291735Z AUTO 11003KT 10SM CLR 31/20 A3004 RMK AO2 T03080202=
SA	29/06/2018 17:15->	METAR KRUQ 291715Z AUTO 00000KT 10SM CLR 31/20 A3006 RMK AO2 T03110199=
SA	29/06/2018 16:50->	METAR KRUQ 291650Z AUTO 04004KT 10SM CLR 30/20 A3007 RMK AO2 T03000202=
SA	29/06/2018 16:35->	METAR KRUQ 291635Z AUTO 06004KT 10SM CLR 31/21 A3007 RMK AO2 T03080206=
SA	29/06/2018 16:15->	METAR KRUQ 291615Z AUTO 09004KT 10SM CLR 30/21 A3007 RMK AO2 T03000205=

METAR/SPECI from KSBY, Salisbury, Salisbury-Ocean City Wicomico County Regional Airport (United States).

SA	29/06/2018 23:54->	METAR KSBY 292354Z 30005KT 10SM CLR 30/18 A3000 RMK AO2 SLP160 T03000178 10333 20289 53005=
SA	29/06/2018 22:54->	METAR KSBY 292254Z 16007KT 10SM FEW050 29/23 A2999 RMK AO2 SLP158 T02940228=
SA	29/06/2018 21:54->	METAR KSBY 292154Z 15005KT 10SM FEW050 31/23 A2998 RMK AO2 SLP155 T03060228=
SA	29/06/2018 20:54->	METAR KSBY 292054Z 15009KT 10SM BKN060 30/22 A2999 RMK AO2 SLP156 T03000222 58009=
SA	29/06/2018 19:54->	METAR KSBY 291954Z 19008KT 10SM SCT060 SCT075 31/22 A2999 RMK AO2 SLP159 T03060217=
SA	29/06/2018 18:54->	METAR KSBY 291854Z 00000KT 10SM CLR 31/22 A3001 RMK AO2 SLP162 T03110217=
SA	29/06/2018 17:54->	METAR KSBY 291754Z 27003KT 10SM SCT050 BKN080 31/21 A3001

		RMK AO2 SLP165 T03060206 10311 20256 51001=
SA 29/06/2018 16:54->		METAR KSBY 291654Z VRB03KT 10SM FEW043 BKN055 31/21 A3001 RMK AO2 SLP163 T03060206=