



Photo 1 – N57477 Right view



Photo 2 – Left and rear view



Photo 3 – N57477 showing substantial damage to right wing struts