

**NATIONAL TRANSPORTATION SAFETY BOARD
RELEASE OF WRECKAGE**

**ACCIDENT/INCIDENT
IDENTIFICATION NUMBER
WPR19FA084**

PART I - RELEASE OF WRECKAGE

REGISTERED OWNER (name and address) Tropical Trading Team LLC [REDACTED] Craig, Colorado 81625		REGISTRATION OR IDENTIFICATION NUMBER N917SR
		MAKE Cirrus
MODEL SR22	DATE OF ACCIDENT/INCIDENT February 15, 2019	LOCATION Ely, Nevada
The National Transportation Safety Board has ☒ has not ☐ completed its investigation of the wreckage described above. All wreckage except that listed on the reverse side is hereby released to the registered owner, or owner's representative, for appropriate disposition. (If no parts are retained, insert NONE.) <u>PARTS RETAINED - SEE BELOW</u>		
SIGNATURE OF NTSB REPRESENTATIVE [REDACTED]	TITLE Senior Aviation Accident Investigator	DATE May 7, 2019

(This section may be signed by a person, not the owner or owner's representative, who has knowledge of the disposition of the wreckage and its parts. Such signature does not place responsibility for disposition of the wreckage upon that person.)

I HEREBY ACKNOWLEDGE:

- ☒ Receipt of the above described wreckage.
- ☐ Removal of the parts, if any, listed on the reverse side of this form.

SIGNATURE [REDACTED]	TITLE MANAGER	DATE 5-7-19
--------------------------------	-------------------------	-----------------------

REMARKS:

This serves as the final release of wreckage for the above described aircraft. The wreckage is hereby released to the owner's representative, Reed Jarman, owner, Air Transport Recovery Services, [REDACTED] Phoenix, Arizona 85009.

Part retained by the NTSB IIC include the following:

- 1) Avidyne DFC90 Autopilot
- 2) Avidyne Primary Flight Display (PFD) circuit board components (4 pieces)