

National Transportation Safety Board
Attention: Mr. Tom Little (NTSB 11C)

[REDACTED]
Federal Way, Washington
98003

Reference Accident Number WPR19FA116

MFR Unison Industries Slick Magneto
Part Number 4371
Serial Number 02051591

6/20/2019

Tom,

The above serial number Slick magneto was tested per manufacturer's requirements and found to function normally. It was tested cold, as received, and then heated to 190 degrees fahrenheit and tested. Electrical components were measured and found to be within specification. The Lycoming magneto drive gear was removed for testing and is bagged separately.

All the best,

Clifton Orcutt
A/P [REDACTED]
Aircraft Magneto Service, LLC

encl invoice