

[REDACTED]

[REDACTED]

I was going back over the photos before I file the report and came across law enforcement photo 20181030_094731_resized.jpg. It is the only onsite photo I found that shows the carb heat; in the other ones it is hidden behind the yoke. In the picture the carb heat is off. I know you mentioned in the report that the pilot didn't turn on the carb heat.



1. Landing Light Switch
2. Navigation Light Switch
3. Master Switch
4. Marker Beacon Switch (OPT)
5. Throttle
6. Carburetor Air Heat Knob
7. Radio Switch (OPT)
8. Primer Knob
9. Propeller Control Knob
10. Generator Warning Light
11. Pitot Heat Switch (OPT)
12. Cabin Air Knob
13. Cabin Heat Knob
14. Mixture Control Knob
15. Rotating Beacon Switch (OPT)
16. Cowl Flaps Control Lever
17. Cigarette Lighter
18. Oil Dilution Switch (OPT)
19. Rotating Beacon Circuit Breaker (OPT)
20. Pitot Heat Circuit Breaker (OPT)
21. Radio Circuit Breaker (OPT)
22. Radio Circuit Breaker (OPT)
23. Radio Circuit Breaker (OPT)
24. Instrument Lights Circuit Breaker
25. Navigation Lights Circuit Breaker
26. Landing Lights Circuit Breaker
27. Generator Circuit Breaker
28. Ignition and Starter Switch

SWITCHES & CONTROLS

