

AIRCRAFT LOG

THE NEW
PIPER AIRCRAFT, INC.

General Offices at
Vero Beach, Florida
U.S.A.

N4161X

Aircraft
Registration number

Part No. 230715

AIRCRAFT DESCRIPTION

Registration No. N4161X

Model: PA-46-350P Popular Name: MALIBU MIRAGE

Serial No.: 4636240 Type Certificate No.: A2550
~~L0225~~ L3205 L6561

Colors: WHITE/OCEANSIDE BLUE & YELLOW

Engine Manufacturer: LYCOMING Serial Numbers: Single L-10342-61A

Original Engine Model: T10-540-AE2A Left _____

Right _____

Propeller Manufacturer: HARTZELL Hub or Serial Number: Single HK494A

Original Propeller Model: HC-13YR-1E Left _____

Right _____

Blade Numbers

Left

Right

368

369

367

1999 MODEL

SERVICE BULLETINS

S/N 4636240

		DATE	TIME	SIGNATURE AND CERTIFICATE NO.
SB 995A	TIT PROBE REPLACEMENT	11/12/01	404.4	
SB 1044	AIRBORNE INSTRUMENT AIR FILTER	12/10/02	530.3	
SB 1048	STAINLESS STEEL CABLES	12/10/02	530.3	
SB 1054	INSPECTION AND MOD OF PILOT AND COPILOT SEATS	12/10/02	530.3	
SB 1060	BRAKE PEDAL BINDING	11/12/01	404.4	
SB 1062	INSPECT INBOARD FLAP DRIVE BELLCRANKS	11/12/01	404.4	
SB 1066	CABIN DOOR LATCH MECHANISM	11/12/01	404.4	
SB 1067(A)	ENTERTAINMENT CONSOLE RESISTOR SHROUD	11/12/01	404.4	
SB 1075	MODIFICATION OF STEERING HORN	11/12/01	404.4	
SB 1087A	REPLACEMENT OF NOSE GEAR EMERGENCY DOWNSPRI	11/12/01	404.4	
SB 1103	ENGINE MOUNT INSPECTION	12/10/02	530.3	
SB 1108	FLUX DETECTOR RELOCATION	N/A	N/A	
VSP-127	LYCOMING SA 59-800- SEE LYCOMING SB 547 FOR N/A	N/A	N/A	
	LYCOMING SB 553 - CRANKSHAFT INSPECTION	12/10/02	530.3	

LETTERS

of
ance

Signature and
Certificate No.

Registration No. _____

and Remarks

Signature

Certificate No.

Advanced Aircraft Service

8622 Gibbs Dr.

San Diego, CA. 92123

858-560-7599 Fax 858-560-7507

CESSNA SERVICE CENTER

Date: 8/22/13 N#: N4161X S/N: 4636240

Hobbs: 1393.7 hr TT: 1393.7 hr TTSMOH:

Installed new prop deice brushes RA1543-7, Installed new nose gear upper
Right trunnion pivot bearing, Resealed left wheel brake cylinder,
C/W SB1193 by installing new 687-931 spring, SB1175B side window inspection,
C/W SB1256 installed 691-339 bolt, SB1103D inspection, SB1048 inspection,
C/W AD84-26-02 installed new P15-1936 air filter,
AD99-15-04 and AD2011-06-10 installed new 86307 TIT probe and checked accuracy,
C/W 12 month ELT inspection and test per FAR 91-207 (d) battery is 06/2014
This Airframe has been inspected I/A/W FAR Part 43 Appendix D. using
Current Aircraft Maintenance Manual as a guide to complete an Annual
Inspection, and was determined to be in an airworthy condition at this time.

END

Registration No. _____

and Remarks

Signature

Certificate No.

Advanced Aircraft Service

8622 Gibbs Dr.

San Diego, CA. 92123

858-560-7599 Fax 858-560-7507

CESSNA / BEECHCRAFT SERVICE CENTER

Date: 1/26/18 N#: N4161X S/N: 4636240

Hobbs: 1689.1 hr TT: 1689.1 hr TTSMOH:

Replaced landing light and emergency fuel pump rocker switch bulbs,

Installed new 301-016-006 tire and 092-308-0 tube on nose wheel,

Adjusted control cables tensions, C/W SB1293C inspection and placards install,

SB1103F mount inspection, SB1193 687-931 spring install, SB1175B inspection,

SB1048 lube, R & R prop S/N HK394A for overhaul by Ameritech Industries

W.O.# 22329-12-2017,

C/W FAR 91.207 (d) ELT inspection and test, battery is due again 10/19

This Aircraft has been inspected I/AW FAR Part 43 Appendix D. using

Current Aircraft Maintenance Manual as a guide to complete an Annual

Inspection, and was determined to be in an airworthy condition at this time.

END