

METARs

Accident 3/30/19 1300 PDT = 2000 UTC

Wx facility 9.5 miles SE of accident location

Time interval: from 03/30/2019 18:00 to 03/30/2019 23:59 UTC

KHQM, Hoquiam, Bowerman Airport (United States).
WMO index: -----. Latitude 46-58-16N. Longitude 123-55-12W. Altitude 4 m.

METAR/SPECI from KHQM, Hoquiam, Bowerman Airport (United States).		
SA	30/03/2019 23:53- >	METAR KHQM 302353Z AUTO 26009KT 10SM CLR 15/08 A3031 RMK AO2 SLP269 T01500083 10156 20078 56021 \$=
SA	30/03/2019 22:53- >	METAR KHQM 302253Z AUTO 25010KT 10SM CLR 16/09 A3033 RMK AO2 SLP273 T01560094 \$=
SA	30/03/2019 21:53- >	METAR KHQM 302153Z AUTO 23011KT 10SM CLR 14/09 A3036 RMK AO2 SLP282 T01440094 \$=
SA	30/03/2019 20:53- >	METAR KHQM 302053Z AUTO 23011KT 10SM CLR 13/08 A3038 RMK AO2 SLP289 T01330083 58017 \$=
SA	30/03/2019 19:53- >	METAR KHQM 301953Z AUTO 23008KT 9SM CLR 12/09 A3039 RMK AO2 SLP295 T01220089 \$=
SP	30/03/2019 19:01- >	<i>SPECI KHQM 301901Z AUTO 21007KT 3SM BR SCT002 09/08 A3042 RMK AO2 T00940083 \$=</i>
SA	30/03/2019 18:53- >	METAR KHQM 301853Z AUTO 21006KT 1 1/4SM BR SCT002 09/08 A3042 RMK AO2 VIS 3/4V2 1/2 SLP303 T00890083 \$=
SP	30/03/2019 18:47- >	<i>SPECI KHQM 301847Z AUTO 20005KT 1 3/4SM BR SCT002 09/08 A3042 RMK AO2 \$=</i>