



RECORD OF CONVERSATION

Joshua D. Cawthra
Senior Aviation Accident Investigator
Western Pacific Region

Date: May 6, 2019
Person Contacted: Stephen Stein (NTSB Investigator)
NTSB Accident Number: WPR19LA117

Narrative:

During a telephone conversation with Mr. Stein, he reported that when he looked at the recovered wreckage of N621JM, he found the brake cable separated from the brake control handle. The cable thimble, clevis pin, and cotter pin remained attached to the brake control handle. Mr. Stein reported that no visible damage was observed to the surrounding cockpit structure and that he would remove both ends of the separated brake cable for further examination.