



RECORD OF CONVERSATION

Samantha Link
Aviation Accident Investigator
Western Pacific Region

Date: May 24, 2019
Person Contacted: Mr. Erik Cook (mechanic)
NTSB Accident Number: WPR19LA130

Narrative:

During a telephone conversation with Mr. Cook he reported that the flight controls were configured properly. All cables remained secured and did not exhibit abnormal wear. The wheels rotated freely, and the brakes exhibited normal operating wear signatures. No anomalies were noted during the examination.

END.

Submitted by: Samantha Link