Wartungsübersicht / *Maintenance record*

Datum: *Date:*	Betriebsstunden: *Engine hours:* Gesamt: *TSN:*	seit letzter GÜ.: *TSO:*	Durchgeführte Arbeiten: *Work performed:*	Unterschrift & LFZ Wart Nr.: *Signature & Licence no.:*
4/3/18	438.9 HOBBS		OIL CHANGE. SERVICED WITH 3 LITERS OF AEROSHELL SPORT PLUS. NEW OIL FILTER. MAGNETIC PLUG CLEAN NO F.O.D. REPLACED MAP CLAMPS PER SI-912i-014. NO LEAKS RETURN TO SERVICE. [redacted]	
26 SEPT 18	468.2		SERVICED ENGINE BY OIL CHANGE. USED 3 LITERS AEROSHEL SPORT PLUS. NEW OIL FILTER. CHECKED MAGNET PICKUP PLUG. NO FOD IN REMOVED FILTER. [redacted]	
24 DEC 2018	470.6		PERFORMED ANNUAL CONDITION INSPECTION ON ENGINE. COMPRESSION #1 79/80 #2 79/80 #3 79/80 #4 79/80. REPLACED SPARK PLUGS WITH NEW ROTAX 297656. REPLACED SPARK PLUG CONNECTOR CAPS WITH	

(CONTINUED)

Wartungsübersicht / *Maintenance record*

Datum: *Date:*	Betriebsstunden: *Engine hours:* Gesamt: *TSN:*	seit letzter GÜ.: *TSO:*	Durchgeführte Arbeiten: *Work performed:*	Unterschrift & LFZ Wart Nr.: *Signature & Licence no.:*
		NEW ROTAX P/N 265-249 CAPS, I CERTIFY THIS ENGINE HAS BEEN INSPECTED IN ACCORDANCE WITH A CONDITION INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION. [redacted]		

ENGINE MODEL:
ENGINE S/N: 4.427.158
REG. NO: N423EB
WORK ORDER:
10848-01-2019

Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 1/18/2019
A/C TSN: 484.6
ENG TT: 484.6
HOBBS: 484.6

Engine Entries

Removed propeller gearbox and drive gear, P/N: 893341, S/N: 57131, and installed new gearbox and drive gear, P/N: 893341, S/N: 74114, IAW BRP-Powertrain MM 72-10-00. Engine run and leak check good.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 1/18/2019 SIGNED: [redacted] Work Order: 10848-01-2019

Travis L Anderson
Certified Repair Station No. L9OR473Y

Printed by EBis 3 (datcomedia.com)

Records of Maintenance, Inspection and Test

Date	Total time since new (airframe)	Records	Approval
		PERFORMED ATC TRANSPONDER TEST AND INSPECTION. THE SYSTEM(s) INSTALLED COMPLY WITH THE REQUIREMENTS OF FAR 91.413 & APPENDIX F OF FAR 43. ACFT. REG: N4235B TACH/AFTT: 470.6 W.O. # 5068 TXPDR#1 MANUFACT: TRIG MODEL# TT-22 S/N: 01622 TXPDR#2 MANUFACT: N/A MODEL# N/A S/N: N/A DATE OF TEST: 12/18/2018 INSPECTOR: [redacted] *Black Mountain Avionics* *1411 Airport Road* *Boulder City, NV 89005* *CRS LVBR789X* *702-294-1044*	
24DEC 2018	470.6	PERFORMED ANNUAL CONDITION INSPECTION AND MAINTENANCE SERVICE. CLEANED + FLUSHED GASCOLATER. CLEANED AIRFILTER KTNSERVICE. REPAIRED CABIN HEAT CABLE. LUBED ALL CONTROLS. FIRE EXTINGUISHER REPLACED WITH SAME NEW. TESTED ELT IN ACCORDANCE WITH FAR 91.207(d) BATERIE DUE FEB 2025. (CONTINUED)	

Date	Total time since new (airframe)	Records	Approval
(CONTINUED)		RUN UP CHECK OK AIRCRAFT OK. I CERTIFY THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANUAL CONDITION INSPECTION AND FOUND TO BE IN AIRWORTHY CONDITION [redacted]	

MAKE: Flight Design Gmbh
MODEL: CTLSi
S/N: F-12-07-05
REG. NO: N423EB
WORK ORDER:
10959-03-2019

Lone Mountain Aviation, Inc.

Repair Station No. L9OR473Y
2830 N. Rancho Dr. Suite A
Las Vegas, NV 89130
Phone: (702) 309-2200

DATE: 3/8/2019
A/C TSN: 493
HOBBS: 493

Airframe Entries

Removed right main tire P/N: TK-2077A, S/N: 052-0916, and tube. Installed new tire P/N: TK-2077A, S/N: 031-0618, IAW Flight Design CTLS MM 4.2.2.

The aircraft and/or component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this facility under the above W.O. number.

DATE: 3/8/2019 SIGNED: [redacted]

Travis L Anderson
Certified Repair Station No. L9OR473Y

Work Order: 10959-03-2019

Printed by EBis 3 (datcomedia.com)