ADS-B OUT

11-10-2017 N4992J Tach 1172.5 Total Time 3908.9
C/W AD 76-07-12 IAW para (1,a,b,c). Next due tach 1272.5
Checked and lube pulleys cables & controls. Test ELT IAW FAR 91.207 para (d). Test OK. ELT battery due Dec 2021. Replace left CVR assembly over left side of carry through spar. Replace push to talk on left yoke. Repack all wheel bearings. Perform landing gear retraction check & emergency extension (test OK).
I certify this Aircraft has been inspected in accordance with an Annual inspection and as of this date return it to service.
[redacted]

Michael Thames A/P [redacted]

	TT	TSO	TACH T	
2-2-18				AiRFrame Log Date 02/02/2018 Tach# 1189.4 N4992J Serviced Nose strut with Nitrogen Rplaced orings RH Brake wheel Cylerder. Replaced Fuel pre. line Hose Assembly 624000-4-0180, Replaced LH Down lock Bulb GE 330. All work in Ref. Piper [redacted] manuals. [redacted]
3-9-18	3936.6	1877.1	1200.2	Replaced aircraft battery with new Concorde RG-35A, ops check was O.K. Commercial Pilot & President of Advantge Aviation [redacted] STC No.: [redacted]
4-18-18	3944.6		1208.2	Removed and Replaced Both main wheel tires P/N 06-05400-3 Goodyear Flitcost III 600-6 6. Re-packed Bearing and Bal-anced wheels. [redacted] A/P [redacted] Lucas Stansdill.
11/07/18	TACH 1205.3 TTAF 3993.7			PERFORMED OPEN/CLOSE, CLEANING SERVICING AND MINOR MAINTENANCE PER THE PIPER SM REV 1/31/08, REMOVED INOP. ADF, & ANTENNAS. NEGLIGIBLE CHANGE TO W/B. SEE INSPECTION REPORT DATED 11/05/18. [redacted] PERFORMED INSPECTIONS OF AD 76-07-12 (10 HR) (ICS SWITCH) PER AD PARA 1(G-C), AD 2017-14-04 (OIL COOLER & HOSE) CW PER SATR-NE-91-01) AD 2018-07-03 (FUEL SEL PLAG) PER AD PARA (a) & SB 1309 PART 1. [redacted]
				SUB-TOTALS this page
				TOTALS—Carry forward to next page

Page No. _____

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page
11/07/18	3993.7		1257.3	
				PERFORMED INSPECTIONS PER THE PIPER SM, SECT. 3, TABLE III-1 REV 1/85
				PES 3H15 THRU 3I2 AS APPLICABLE. "I CERTIFY THAT THIS AIRCRAFT
				HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION
				AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION" —
				[redacted] STOCSDILL
11/07/18	TACH 1257.3			
				PERFORMED INSPECTIONS OF ELT PER FAR 91.207 d (1-4) FOR
				PROPER OPERATION. BATT EXP. DATE 12/21 [redacted]
2/13/13	Tach 1269.4			
				Performed Installation of propeller, per Piper Aircraft Co,
				PA-28R-180 8A-7 (Sec, a-j), Replaced Alternator Belt —
				MCT3265-015 & Brackets [redacted]
3/5/19	TACH 1281.4			
				INSTALLED UAVIONIC SKY BEACON UAXG0032-01, s/n 1001849 SEE 337
				THIS DATE. READY FOR FAA CERTIFICATION FLIGHT. [redacted]
				[redacted] STOCSDILL
				s/n 1001849.
				SSID: Beacon-7DA0
				Pass: KiloLight
				SUB-TOTALS this page
				TOTALS—Carry forward to next page