



SUMMARY OF FINDINGS

Tealeye Cornejo

Air Safety Investigator (Field)

Western Pacific Region

Date: 05/22/2019

Person Contacted: Samantha Link NTSB **email:** [REDACTED]

NTSB Accident Number: WPR19LA165

Narrative:

According to ASI Link, the pilot reported that he turned to base to return to the airport, when the engine quit. The pilot stated that he had 20 gallons of fuel. The pilot stated that the engine gave two big jerks and quit. He landed in a field just short of the runway and the airplane struck tree stumps. The airplane gear separated, a branch struck the tail and dented it.