



Photo 1 – Airplane Following Recovery from the Accident Site



Photo 2 – Top Spark Plugs



Photo 3 – Bottom Spark Plugs



Photo 4 – Carburetor Venturi with Valve Seal



Photo 5 –Valve Seal Material




Photo 6 – Carburetor Heat Butterfly Valve with Carb in the Heat ON Position. Viewed from Filtered Air Inlet. Missing Seal Highlighted.



Photo 7 - Carburetor Heat Butterfly Valve with Carb in the Heat OFF Position. Viewed from Filtered Air Inlet. Missing Seal Highlighted.



Photo 8 - Carburetor Heat Butterfly Valve with Carb in the Heat ON Position. Viewed from Hot Air Inlet. Missing Seal Highlighted.