

CESSNA 182RG N5JB

SUBJECT: FLAP SETTING

Right and left flap rollers bottomed out:

Right Flap 34° approx.

Left Flap 35° approx.

The Maintenance Manual shows 40" flap setting for that year C182RG

NOTE:

This information provided by recovery technician at Arlin's Aircraft.

Specific method and references for flap extension angle not verified by FAA or NTSB personnel