

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Mesa State: AZ
 ZIP: 85212 Country: USA
 Latitude: 3316'59.8N Longitude: 111034'24.7W
(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 08/14/2019 Local Time: 0725
mm/dd/yyyy
 Time Zone: MST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☐ None

AIRCRAFT INFORMATION

Registration Number: N19AM

Manufacturer: EXTRA Flugzeugproduktions - und Vertriebs - GmbH

Model: 300L

Serial Number: 046

Year of Manufacture: 1997

Amateur-Built: ☐ Yes ☒ No
 If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

- ☐ IFR-Equipped and Certified
☐ Commercial Space Flight
☐ Unmanned Aircraft

Maximum Gross Weight: 2095 lbs

Weight at Time of Accident/Incident: 1400 lbs

Number of Seats: 2 Flight Crew Seats: 1

Cabin Crew Seats: _____ Passenger Seats: 1

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate (Check all that apply)

Standard

- ☐ Normal
☒ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility

Special

- ☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

- ☐ Retractable
☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

- ☐ Carburetor ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. <i>mm/dd/yyyy</i>	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Lycoming	AEIO-540-L1B5	L-26069-48A		300	1360		1360
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☒ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: See Log Books
mm/dd/yyyy

Airframe Total Time: 3231 hrs

hours measured at (Select one)

- ☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☒ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
☐ Specify: _____

Propeller 1

- ☐ Fixed Pitch
☒ Controllable Pitch
☐ Ground Adjustable

Manufacturer: MT-3

Model: MTV-9-B-C/C200-15 (3 Blade)

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☒ C126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☒ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft: ☒ Yes ☐ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
☐ Airframe Parachute
☐ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☐ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☒ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: OP Aviation & Consulting LLCCity: GlendaleState: AZZIP: 85308Fractional Ownership Aircraft: ☐ Yes ☒ No

Country: _____

Operator of Aircraft☐ Same As Registered Owner☐ Same Address as Registered OwnerName: Aviation Performance Solutions LLCCity: Mesa

Doing Business As: _____

State: AZZIP: 85212

Air Carrier/Operator Designator (4 Character Code): _____

Country: USA**Operating Certificates Held**

(Check all that apply)

- ☐ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☒ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437

☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial

☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International

☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☒ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☐ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: Phoenix-Mesa GatewayDistance From Airport Center: 3.6 smAirport Identifier: KIWADirection From Airport: 086 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 1380 ft. msl**Runway Information**

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Final ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Philip

City of Residence: Glendale

Middle Initial: A.

State: AZ ZIP: 85308

Last Name: Oppenheimer

Country: _____

Age at time of Accident/Incident: 61 Date of Birth: _____ mm/dd/yyyy

Certificate Number: _____

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☒ Rear ☐ Center ☐ Single	Restraint Type Available ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown Used ☐ None ☐ Lap only ☐ 3-point ☐ 4-point ☒ 5-point ☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☒ Flight Instructor ☒ Commercial ☐ US Military ☐ Private ☐ Recreational ☒ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer			
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☐ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☒ Class 2 ☐ Unknown	Medical Certificate Validity ☐ Without limitations/waivers ☐ Unknown ☒ With limitations/waivers ☐ N/A ☐ Special Issuance	Date of Last Medical <u>10/31/2018</u> mm/dd/yyyy

Medical Certificate Limitations

Must have available glasses for near vision.

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: 7/30/2018
mm/dd/yyyy

Flight Review Aircraft

Make: EXTRA Flugzeugproduktions - und Vertriebs - GmbH

Model: 300L

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☒ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☐ None ☒ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☐ None ☒ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☒ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
--	---	--	--

Type Ratings

BE-400, MU-300, Authorized Experimental: CE-T37, DC-A4, DO-AJET, NH-T38, S-211

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	11,000	2,170	8,341	2,697						
Pilot in Command (PIC)	10,780	2,170	8,300	2,570						
Time as Instructor	3,685	2,000	2,685	1,000						
This Make/Model										
Last 90 Days	75	51								
Last 30 Days	26	21								
Last 24 Hours	1	1								

"FLIGHT CREWMEMBER 2" INFORMATION**"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident**

☐ Pilot ☐ Co-Pilot ☒ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 2" Identification

First Name: Richard

City of Residence: Norton

Middle Initial: _____

State: MA ZIP: 02766

Last Name: Marsolais

Country: USA

Age at time of Accident/Incident: 42 Date of Birth: _____ mm/dd/yyyy

Certificate Number: _____

Degree of Injury

☒ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☒ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☒ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☒ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☒ Commercial ☒ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☒ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

____ mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Issuance****Date of Last Flight Review
or Equivalent, Including
FAR 121/135 Checks:**

____ mm/dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s)

(Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings**Student Endorsements (Include dates)**

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	3,700	0								
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)

Crew Name and Address	Seat Occupied	Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____	☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Private ☐ Recreational ☐ Student ☐ Sport ☐ Commercial ☐ US Military ☐ Airline Transport ☐ Foreign ☐ Flight Engineer	Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No	Total Flight Time at the Time of this Accident/Incident: _____ hrs	

Crew Name and Address	Seat Occupied	Injury
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____	☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Private ☐ Recreational ☐ Student ☐ Sport ☐ Commercial ☐ US Military ☐ Airline Transport ☐ Foreign ☐ Flight Engineer	Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No	Total Flight Time at the Time of this Accident/Incident: _____ hrs	

PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)

Name and Address	Seat	Injury	Restraint Type	Inflatable Restraints	Age
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other	☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KIWA</u> City: <u>Mesa</u> State: <u>AZ</u> Country: <u>USA</u>	Time of Departure Time: <u>0625</u> Time Zone: <u>MST</u>	Destination Airport ID: <u>KIWA</u> City: <u>Mesa</u> State: <u>AZ</u> Country: <u>USA</u>	Type Flight Plan Filed ☐ None ☐ VFR/IFR ☒ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☒ Yes ☐ No ☐ Unknown
--	--	---	--

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☒ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A	☒ Class G	☐ Military Operations Area (MOA)	☐ Special	Altitude of In-Flight Occurrence: <u>8200</u> ft msl
☐ Class B	☐ Demo Area	☐ Airport Advisory Area	☐ Air Traffic Control Area	
☐ Class C	☐ Warning Area	☐ Jet Training Area	☐ Unknown	
☐ Class D	☐ Prohibited Area	☐ TRSA		
☐ Class E	☐ Restricted Area	☐ FAR 93		

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE**Source of Pilot Weather Information***(Check all that apply)*

☒ National Weather Service	☐ Company
☐ Flight Service Station	☐ Military
☐ TV/Radio	☐ Internet
☒ Automated Report	☐ None
☐ Commercial Weather Service (DUATS)	☐ Unknown
☐ On-Board Weather	

Weather Observation Facility

Facility ID: KIWA ATIS (Departure) / Tower
Observation Time: 0620 (ATIS) / 0720 (Tower)
Time Zone: MST
Distance from Accident Site: 3 nm
Direction from Accident Site: 266 degrees true

Basic Conditions

- ☒ VMC
☐ IMC
☐ Unknown

Light Condition

- ☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

- ☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Ceiling

- ☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Temperature: _____ (C) or 90 (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: _____ in. Hg
or _____ MB**Lowest Cloud Condition Height**N/A ft agl**Ceiling Height**N/A ft agl**Wind Direction**

- ☐ Variable

-or-

Direction: 150 degrees true**Wind Speed**

- ☐ Calm
☐ Light and Variable

-or-

Speed: 7 kts**Wind Gusts**

- ☐ Not Gusting

-or-

Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 3000 ft**Intensity of Precipitation**

- ☐ Light
☐ Moderate
☐ Heavy
☒ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

- | | | |
|---------------------------------------|---------------------------------------|---|
| ☐ None | ☐ Drizzle | ☐ Freezing Rain |
| ☐ Rain | ☐ Ice Pellets | ☐ Snow Shower |
| ☐ Snow | ☐ Snow Pellets | ☐ Ice Pellets Shower |
| ☐ Hail | ☐ Snow Grains | ☐ Freezing Drizzle |
| ☐ Rain Showers | ☐ Ice Crystals | |

Restriction to Visibility (Check all that apply)

- | | |
|--|-------------------------------------|
| ☒ None | ☐ Fog |
| ☐ Blowing Dust | ☐ Ground Fog |
| ☐ Blowing Sand | ☐ Haze |
| ☐ Blowing Snow | ☐ Ice Fog |
| ☐ Blowing Spray | ☐ Smoke |
| ☐ Dust | ☐ Unknown |

Icing Forecast

- | Amount | Type |
|---------------------------------------|-------------------------------|
| ☒ None | ☐ N/A |
| ☐ Trace | ☐ Rime |
| ☐ Light | ☐ Clear |
| ☐ Moderate | ☐ Mixed |
| ☐ Severe | ☐ Unknown |
| ☐ Unknown | |

Icing Actual

- | Amount | Type |
|---------------------------------------|-------------------------------|
| ☒ None | ☐ N/A |
| ☐ Trace | ☐ Rime |
| ☐ Light | ☐ Clear |
| ☐ Moderate | ☐ Mixed |
| ☐ Severe | ☐ Unknown |
| ☐ Unknown | |

Turbulence

- | Type (Check all that apply) | Severity |
|--|-----------------------------------|
| ☒ None | ☐ Light |
| ☐ Clear Air | ☐ Moderate |
| ☐ Terrain-Induced | ☐ Severe |
| ☐ Convective Turbulence | ☐ Extreme |

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Landing gear detached from aircraft and propeller damaged on impact, wing and underbelly damage.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

1. On 14 Aug 2019, I was the PIC, mishap pilot (MP) and acting CFI on the mishap aircraft (MA) Extra 300L, N19AM. Richard Marsolais was my student. He is a U.S. Army King Air 200 pilot. The mission was being conducted as part of Aviation Performance Solutions' (APS') Professional Pilot Upset Training (PPUT) Syllabus.
2. The MA departed KIWA at approximately 0625L (1325Z). The MA engine failure occurred at approximately 0715L (1415Z) approximately 9NM ESE of KIWA. The mission was being conducted in its designated training area (also approximately 2NM E of AZ38-Rittenhouse AHP). Weather was VFR/VMC. Winds were approximately 150/07. Altitude at the time of engine failure was approximately 8200' MSL/6700' AGL.
3. The MP completed a rolling maneuver demonstration with the MA as part of the UPRT profile. Upon roll-out, the engine suddenly lost power and the MP was not able to maintain altitude.
4. The MP immediately switched the fuel selector valve from the Wings position to the Center & Acro fuel tank position per POH guidance (most reliable tank and reading just below Full fuel), turned the MA towards the nearest suitable airfield (KIWA), gained as much altitude as the remaining airspeed and engine performance would allow and set up an optimum glide profile at 80 KIAS (best glide speed per the POH based on weight of the aircraft). Based on cockpit indications, the MP assessed that the engine was still operating under partial power (~1800 RPM). The MP performed the POH-prescribed emergency procedures for Engine Failure in Flight, contacted KIWA Tower and declared an Emergency.
5. The pilot advised KIWA Tower that reaching the airport looked likely (based on visual assessment. There was a quartering tailwind from the southeast as reported by the control tower on initial contact. The tower deconflicted all traffic and cleared the airplane to land on any runway. Runway 30R, the closest runway, was selected by the MP.
6. The MP noted that there was sufficient fuel on-board for the airplane to safely return to the airport with more than required fuel reserves. The emergency fuel boost pump was confirmed to be on. The MP also attempted to get engine power back by switching the fuel selector back and forth between both fuel tanks (Center & Acro and Wings) with no effect. The MP then left the selector valve on the fullest tank (Center & Acro), the internal fuselage fuel tank. The MP also confirmed the mixture was set to full rich and the ignition BOTH position was selected. Other than an apparent loss of power response experienced by the MA, the engine instruments otherwise indicated normal operating temperatures, pressures, and quantities consistent with a lower engine speed (~1800 RPM). The MP also attempted to ascertain power status and response by manipulating the throttle. There was no indicated engine response when moving the throttle from idle to full power and back (several times). Approximately one minute into the glide, the engine and glide performance were again assessed by the MP as sufficient to return to KIWA at an optimum glide profile under what appeared to be a partial power situation.
7. Approximately 4 minutes after the power loss was encountered, and approximately one minute prior to touchdown, an unexpected further reduction in engine performance began to occur (to ~1500 RPM). The engine and glide performance were again assessed by the MP and he concluded further remedial action would be required to sustain the glide profile required to land at KIWA. The MP placed the propeller control in the "feather" position (coarse pitch/low drag). However, it was noticed that when this was attempted, the propeller RPM reduced but the propeller blades remained in the high pitch/high drag position. The MP felt the aircraft slow and noted an increase in rate of altitude loss. The MP returned the propeller control to full forward and reestablished the 80 KIAS glide profile (this also slowed the descent rate). Propeller RPM continued to decay below 1500 RPM with a subsequent assessment that the KIWA runway could no longer be reached. The pilot immediately transitioned to an off-field emergency forced landing profile.
8. The MP notified the student and KIWA Tower of the situation and the change to an off-airport landing. The MP then performed a gliding right turn back into the wind, selected the best available safe landing area, and carried out an emergency off-airport landing.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Pending NTSB Investigation.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**
(Convert from pounds, as necessary)25 Gallons**Fuel Type**☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive

Other Services, if Any, Prior to Departure

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☐ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Crew members performed an emergency ground egress after the aircraft had come to a stop. The PIC MP opened the canopy, both crew members unstrapped and egressed the aircraft. They then moved to a safe distance away from the aircraft (approximately 300 feet). Before exiting the aircraft, the MP confirmed that all electrics, fuel and power switches were placed in the off/safe/normal positions and that the fuel selector valve was placed in the Emergency Fuel Shutoff position per the POH checklist(s).

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number****Manufacturer:** _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

08/15/2019

mm/dd/yyyy

Name of Pilot/Operator: Philip A. Oppenheimer

Signature:

-- or --

☐ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --

☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

WPR19LA218

Reviewed by NTSB Regional Office

WPR

Name of Investigator

D. Hogenson

Date Report Received

08/19/2019