

The part number for the specific section that failed is 19-353632-14. The attached picture provides a visual of the piece that failed (large piece of the duct missing in the photo). The highlighted picture below shows the precise location of the failure.

