



Photo 1 – N6064H, top-side view, showing damage to the fuselage, and main rotor system. Photo courtesy of the owner.