



Photo 1 – View of nosed over biplane with damaged wings and empennage (courtesy of the operator)