



Photo 1 – View of damage to the vertical stabilizer and the rudder (Courtesy of Pilot)