Page No. _____

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		TOTAL brought forward from previous page	
11-22-17		Tach 139.5 Total 2416.7	This aircraft has been inspected in accordance with an annual inspection & has been determined to be in an airworthy condition. Drained all fuel sumps. cleaned electric boost pump screen. charged aircraft battery + checked electrical systems. Installed new power supply to RH strobe. (PN 152-0007) ELT check ok as per FAR 91.207(d). Batt. exp. date: 12-18. Inspected flight control systems. Inspected aileron control system as per AD 79-22-04. Installed new outboard aileron hinge bushing PN 902013-1 on both ailerons. serviced tires. Packed wheel bearings. checked brake linings + serviced master cylinders. Adjusted nose wheel castering at 20 lbs. ADs checked thru 17-22.
			[redacted]
12-3-18		Tach 215.8 Total 2498.0	This aircraft has been inspected in accordance with an annual inspection + has been determined to be in an airworthy condition. Drained all fuel sumps + cleaned electric boost pump screen. charged aircraft battery + checked electrical systems. Installed new strobe power supply PN 152-0007 in RH wing tip. Installed new ELT battery PN BP1010. Exp. date: Feb. 2021 ELT check ok as per FAR 91.207(d). Inspected flight control systems. Inspected aileron control systems in accordance with AD 79-22-04. No defects. serviced tires. Packed wheel bearings. checked
		SUB-TOTAL this page	
		TOTAL—Carry forward to next page	

Page No. _____

DATE	TOTAL TIME IN SERVICE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		TOTAL brought forward from previous page	
			brake lines & serviced Master cylinders. serviced nose strut swivel assy. Tension set @ 17 lbs. AD's
			checked thru 18-23. [redacted]
8-26-19			Tach 264.9 Installed new electric boost pump AN TAE8-2100-3 supplied by Flatabar. Leak check ok. [redacted]
			SUB-TOTAL this page
			TOTAL—Carry forward to next page

DATE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED – SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
		with 8 qts. Phillips 20W50. Installed new
		oil Filter. Old Filter inspected for contamination
		None present. cleaned, gapped + rotated
		spark plugs. Removed both magnetos. Adjus-
		ted points + internal timing to specifications.
		Mags reinstalled on engine, to 25° BTC. In-
		spected muffler + exhaust heat exchangers.
		Installed new induction air Filter, checked
		engine controls for proper rigging. Drained
		carb bowl. cleaned carb in-let fuel screen.
		ADs checked thru 16-20.
		[redacted]
10-27-17		Oil & Filter Changed 129 Hrs Tach Time MA
11-22-17	Tach 137.5	Total 6304.3 SMOH 228.1 This engine has been
		inspected in accordance with a 100hr inspection & has been
		determined to be in an airworthy condition. compression
		check; #1-78, #2-74, #3-77, #4-77. oil + Filter not changed
		at this time. Inspected oil filter removed @ tach 129.0 for
		contamination. None present. cleaned + rotated spark plugs.
		checked magneto timing (25° BTC) Installed new induction
		air Filter. Drained carb bowl. cleaned carb in-let fuel
		screen. checked engine controls for proper rigging.
		Inspected muffler + exhaust heat exchangers. Adjusted
		alternator drive belt. ADs checked thru 17-22.
		[redacted]
		Note: AD 17-16-11 does not apply to this engine. PN
	SL 1392	3A piston pin bushings were installed @ OH

Page No. _____

DATE	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED – SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
12-3-18	Tach	215.8 Total 2493.0 Total 6380.6 SMOH 304.4
		This engine has been inspected in accordance
		with a 100 hr. inspection & has been determined
		to be in an airworthy condition. compression
		checks; #1-79, #2-75, #3-78, #4-75. Oil changed
		with 8 qts. Phillips 20W50. Installed new oil
		filter. Old Filter inspected for contamination.
		None present. cleaned & rotated spark plugs.
		checked magneto timing (25° BTC). Drained
		carb bowl. cleaned carb in-let fuel screen. In-
		stalled new Brackett induction air Filter P/N
		BA20. checked engine controls for proper
		rigging. Inspected muffler & exhaust heat
		exchangers. AD's checked thru 18-23.
		[redacted]
8-1-19		Tach 265 Hrs Oil & Filter Changed
		Phillips X-C 20-50
11-5-19		Tach 315 Hrs Oil & Filter Changed
		Phillips X-C 20-50