



SUMMARY OF FINDINGS

Tealeye Cornejo

Air Safety Investigator (Field)

Western Pacific Region

Date: December 21, 2019

Person Contacted: Sgt. Benker; Goodyear PD

NTSB Accident Number: WPR20FA049

Narrative:

Responding law enforcement reported that the airplane had impacted high-tension power lines about a mile south of the airport. They estimated that height of the power lines to be about 100 ft. above ground level (agl) and were unmarked and unlighted.