

Recorders Summary Report

The Vehicle Recorder Division received a RDM file, as well as a Garmin Perspective PFD (s/n unknown) and MFD (s/n unknown). The Garmin devices arrived exhibiting signs of thermal damage (PFD.JPG and MFD.JPG). Due to the damage, no data could be recovered from the devices.

The RDM file contained data from between 12/3/2019 to 12/27/2019. The last session recorded on 12/27/2019 was determined to be pertinent to the accident.

Plot1_Overview is a plot of pertinent recorded parameters during the entire event.

Attachment1.csv is the tabular data associated with the accident event.

Michael Portman
Aerospace Engineer – Recorder Specialist
National Transportation Safety Board




Figure 1 - MFD




Figure 2 - PFD

Prepared by: Michael Portman, Recorder Specialist, NTSB RE-40