



Photo 1 – Smoke rising from armrest (Source: Pilot).



Photo 2 - Flames engulfing airplane cabin (Source: Pilot).




Photo 3 - Audio cards and (smaller) microphone card inside the panel wall (Source: Cirrus).




Photo 4 - Audio card with (top) and without (bottom) heat-shrink sleeving and with the input filter capacitors circled.



Photo 5 - Accident airplane after fire was extinguished.



Photo 6 - Audio card exhibiting burnt resistor (Source: Cirrus).