



Photo 1 – N204BF at the accident site. Photo courtesy of the operator.



Photo 2 – Left-side view. Photo courtesy of the operator.



Photo 3 – Rear-view, showing substantial damage to the left wing



Photo 4 – Right-side view showing the fuselage damage from the BRS right-rear suspension cable. Photo courtesy of the operator.