



RECORD OF CONVERSATION

Andrew L. Swick
Aviation Accident Investigator
Western Pacific Region

Date: October 12, 2021
Person Contacted: Mr. Riley Wilson (Student Pilot)
NTSB Accident Number: WPR20LA110

During the initial call following the accident, Mr. Wilson reported to the NTSB on-call duty officer, that the flight was a local instructional flight, and he believed there was a mechanical issue with the airplane. While on final approach to runway 29 at the Ralph Wenz Field Airport (PNA), Pinedale, Wyoming, the flight instructor took control of the airplane due to the airplane drifting to the right. Shortly after, about 50 to 100 ft above ground level, the “airplane corkscrewed into the ground.” Mr. Wilson stated he bought the airplane about two weeks prior.



Andrew L. Swick
Aviation Accident Investigator
National Transportation Safety Board
Western Pacific Region

RECORD OF CONVERSATION