



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in charge

NTSB Accident Number: WPR20LA135
Aircraft Registration & Make/Model: N6521Y / Piper PA-23-250
Accident Location: Hemet, CA.
Accident Date: April 30, 2020

An autopsy of the pilot was performed by the Riverside County Sheriff's Department, Coroner-Public Administrator. The cause of death was listed as blunt trauma.