

Aircraft Record General Information

Manufacturer DANNE B EVANS Model ZENITHAIR CH-601HDS

Serial 6-3704 Registration Number N6402X

Date of Manufacture 07/16/02

Engine(s) currently installed:

Manufacturer PZL-FRANKLIN Model PZL-F4A235B31 Serial 2611300034

Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer IVOPROP INC Model MR268 Q-FRAN.

NUB Model _____ Serial 12M8-02 Serial _____

Blade Model MAGNUM Serial _____ Serial _____ Serial _____

Blade Model _____ Serial _____ Serial _____ Serial _____

YEAR: 2019 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
10-15	982.4		982.4	Pre-owned condition Inspection I/A/w scope and detail of FAR 43 appendix D ANNUAL Inspection and was determined to be in airworthy condition. Installed new brake lining on both LHK Main wheels and serviced, Inspected and tested ELT I/A/w FAR 91-2074 battery exp. date 12-2025 I certify that this <u>Aircraft</u> has been inspected in accordance with a <u>ANNUAL</u> inspection and was determined to be in airworthy condition. Alberto Marin AP [REDACTED] IA

Engine Record General Information

Manufacturer PZL-FRANKLIN

Model PZL-F4A235B31

Serial 2611300034

Type Certificate

This engine is currently installed in aircraft ZENITHAIR CH-601HDS N6402X

SER# 6-3904

Minimum Octane Fuel

Oil Grade: Summer

Winter

Magneto Time

32° BTC

Point Setting

Firing Order 1, 4, 2, 3

Spark Plug Gap

.017

Manufacturer recommended overhaul at

hours

YEAR: 02 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician at Repair Facility. (See back pages for other specific entries.)
02/14				FILLED CRANKCASE WITH 6 QT OF AEROSHELL 100 MINERAL OIL [REDACTED]
8/5	6.5		6.5	INSTALLED OIL COOLER OT NOW RUNS 160-180 [REDACTED]
8-14	9.3		9.3	C/W VIB SB, PZL-F/68/2002 REPLACED FUEL PUMP. [REDACTED]
8/19	17.3		17.3	CHANGED OIL install 6 QTS AEROSHELL 100 [REDACTED]

YEAR: 02 DATE	RECORDING TACH TIME
9/17	45.9
4/1/03	65.0
07/	
11/04	101.0
06/25	119.0

