



Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
IIC

NTSB Accident Number: WPR20TA039
Aircraft Registration & Make/Model: N65RS / Enstrom F28F
Accident Location: Riverton, UT.
Accident Date: December 11, 2019

During the interview with the pilot, he stated that he did not have a pilot's certificate. A search on the Federal Aviation Administration (FAA) website confirmed his statement. See Figure 1.

Search Options

We do not display SSN, certificate number, or date of birth. We will display a releasable address in accordance with the [Aviation Investment and Reform Act for the 21st Century](#). We display medical information based on FAA's [Civil Aerospace Medical Institute](#) (CAMI) medical records. If the medical dates are incorrect, please contact CAMI at (405) 954-4821. To check the validity of the certificate, email a request to Aviation Data Systems Branch, g-amc-afs620-pai@faa.gov.

You can now search airmen by last name, last name and certificate number, or last name and other advance criteria such as first name, date of birth or city. You may also search by Parachute Seal Symbol.

* Required

* Last Name: Certificate Number: (* Requires last name)

First Name: (may be partial or include middle name)

Date of Birth: Day: Year: (e.g. 1974)

City:

State:

- OR - Country:

OR

Parachute Seal Symbol:

Search Results ☐ Horizontal ☒ Vertical

No records found based on search criteria provided above.

Figure 1. Image from the FAA airmen inquiry showing no certificate for anyone in Utah with the name Dennis Goggin.