



Photo 1 – View of damage to the helicopter main rotor and tail rotor systems (Courtesy of FAA)