



Condition Inspection

N87GX S/N: 351

October 29, 2020

TTAF: 317.9

TTE: 317.9

New Matco brake liners installed per Remos Maintenance Manual Section 5.

Engine mounts torque verified to 35 Nm per Remos Maintenance Manual Section 11.

Lubricated all control surface joints and pushrods.

Updated Dynon D100 to final release 5.6.1 per Dynon Update Instructions.

No new Remos Safety Alerts / Directives at the time of inspection, all complied with.

I certify that this aircraft has been inspected in accordance with the Remos Annual Condition Inspection Checklist as identified in the aircraft's instructions for continued airworthiness (ICA) on this date and is found to be in a condition for safe operation.