

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Indian Creek Canyon State: UT

ZIP: 84532 Country: USA

Latitude: 38.1988 Longitude: -109.7063

(Enter in decimal degrees or degrees minutes seconds)

Accident/Incident Date/Time

Date: 11/12/2020 Local Time: 08:20
mm/dd/yyyy

Time Zone: MST

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N721P

Manufacturer: Maule

Model: MX-7-180AC

Serial Number: 33009C

Year of Manufacture: 2004

Amateur-Built: ☐ Yes ☒ No If Yes ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 2400 lbs

Weight at Time of Accident/Incident: 1900 lbs

Number of Seats: 4 Flight Crew Seats: 2

Cabin Crew Seats: 0 Passenger Seats: 2

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☒ Utility
☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☐ Tricycle ☒ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating ☐ Liquid Rocket
☐ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

☒ Carburetor ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☒ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng 1	<u>Lycom ng</u>	<u>O-360-C4F</u>	<u>unknown</u>	<u>unknown</u>	<u>180</u>	<u>1400</u>	<u>35</u>	<u>n/a</u>
Eng 2								
Eng 3								
Eng 4								

Last Inspection Type

- ☐ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☒ Annual ☐ Unknown

Date Last Inspection: 08/01/2020
mm/dd/yyyy

Airframe Total Time: 1400 hrs

hours measured at (Select one)

☐ Last Inspection ☒ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
☐ Conditional (Amateur-built only)
☐ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Class C handheld extinguisher mounted under pilot seat

Propeller 1

- ☒ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Senesich

Model: 78EM8S8-0-56

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes

ELT Manufacturer: EBC

Model or Part No.: EBC-302

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☐ Yes ☒ No

Did ELT Activate? ☒ Yes ☐ No

If activated

Did ELT Aid in Locating Aircraft: ☐ Yes ☒ No

If not activated

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
☐ Airframe Parachute
☒ Angle of Attack Indicator
☐ Autopilot
☐ Data Recorder
☒ Electronic Flight Bag or Handheld Device
☐ Electronic Multifunction Display
☐ Electronic Primary Flight Display
☐ Handheld GPS
☐ Heads Up Display
☐ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Robert Oliver Parke LoydCity: TempeState: AZZIP: 85287Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: USA**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____

ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)

Airport Name: _____

Distance From Airport Center: _____ sm

Airport Identifier: _____

Direction From Airport: _____ degrees true

Proximity to Airport: ☐ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/A

Airport Elevation: _____ ft. msl

Runway Information

Runway ID: _____ (L/R/C) Length: _____ ft Width: _____ ft

Runway/Landing Surface (Check all that apply)

- ☐ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☐ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: Robert City of Residence: Tempe
 Middle Initial: O P State: AZ ZIP: 85287
 Last Name: Loyd Country: _____
 Age at time of Accident/Incident: 34 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury ☐ None ☐ Fatal ☒ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☒ 3-point</td> <td>☒ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☒ 3-point	☒ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Available	Used																
☐ None	☐ None																
☐ Lap only	☐ Lap only																
☒ 3-point	☒ 3-point																
☐ 4-point	☐ 4-point																
☐ 5-point	☐ 5-point																
☐ Unknown	☐ Unknown																
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☒ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☒ Flight Engineer		Medical Certificate Validity ☒ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance															
Principal Occupation ☒ Pilot ☐ Other ☐ Unknown	Medical Certificate ☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown		Date of Last Medical <u>01/21/2016</u> mm/dd/yyyy														

Medical Certificate Limitations

None

Medical Certificate Special Issuance

n/a

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

12/04/2018
mm/dd/yyyy

Flight Review Aircraft

Make: Maule

Model: MX7-180-AC

Airplane Rating(s) (Check all that apply) ☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) (Check all that apply) ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) (Check all that apply) ☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) (Check all that apply) ☒ None ☐ Instrument Airplane ☐ Airplane Single-Engine ☐ Instrument Helicopter ☐ Airplane Multi-Engine ☐ Helicopter ☐ Gyroplane ☐ Glider ☐ Powered Lift ☐ Sport
---	---	--	--

Type Ratings

Ta whee
H gh Performance

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	468.8	262.2	468.8	0	40.9	0	6.7			
Pilot in Command (PIC)	391.2	245.2	391.2	0	34.9	0	0			
Time as Instructor	0	0	0	0	0	0	0			
This Make/Model					31.9	0	0			
Last 90 Days	28.9	28.9	28.9	0	6.0	0	0			
Last 30 Days	15.8	15.8	15.8	0	3.2	0	0			
Last 24 Hours	0	0	0	0	0	0	0			

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☐ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury

☐ None ☐ Fatal
☐ Minor ☐ Unknown
☐ Serious

Seat Occupied

☐ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military
☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign
☐ Student ☐ Sport ☐ Flight Engineer

Principal Occupation

☐ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3
☐ Class 1 ☐ Driver's License (Sport Pilot only)
☐ Class 2 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers ☐ Unknown
☐ With limitations/waivers ☐ N/A
☐ Special Issuance

Date of Last Medical

_____ mm/dd/yyyy

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

_____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
 Model: _____

Airplane Rating(s) (Check all that apply)

☐ None
☐ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☐ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☐ None ☐ Instrument Airplane
☐ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multi-Engine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered Lift ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer					Restraint Type: Available Used ☐ None ☐ None ☐ Lap Only ☐ Lap Only ☐ 3-point ☐ 3-point ☐ 4-point ☐ 4-point ☐ 5-point ☐ 5-point ☐ Unknown ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: <u>Murtidevi</u> City: <u>Englewood</u> Middle Initial: _____ State: <u>CO</u> ZIP: <u>80110</u> Last Name: <u>Nauth</u> Country: <u>USA</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: _____	☐ None ☒ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☒ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>n/a</u> City: <u>lat long 38.1988, -109.7063</u> State: <u>Utah</u> Country: <u>USA</u>	Time of Departure Time: <u>08:20</u> Time Zone: <u>MST</u>	Destination Airport ID: <u>U64</u> City: <u>Monticello</u> State: <u>Utah</u> Country: <u>USA</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
--	---	--	---

Type of ATC Clearance/Service (Check all that apply)

☒ None	☐ Special VFR	☐ Special IFR	☐ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>n/a</u> ft msl
--	--	---	---	---

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service	☐ Company
☐ Flight Service Station	☐ Military
☐ TV/Radio	☒ Internet
☐ Automated Report	☐ None
☐ Commercial Weather Service (DUATS)	☐ Unknown
☐ On-Board Weather	

Weather Observation Facility

Facility ID: BIVU1
 Observation Time: 07:45
 Time Zone: MST
 Distance from Accident Site: 20.5 nm
 Direction from Accident Site: 85.8 degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☐ Few ☒ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

> 5000' ft agl

Ceiling

☐ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☒ Overcast ☐ Unknown

Ceiling Height

> 5000' ft agl

Temperature: _____ (C) or 38 (F)

Dew Point: _____ (C) or 14 (F)

Altimeter Setting: unknown in Hg
 or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 150 degrees true

Wind Speed

☐ Calm
☒ Light and Variable

-or-
Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility >10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: 4,800 ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☐ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

NOTAMs n/a, accident was off airport
 G-AIRMET ZULU freezing level sfc-12000 MSL in effect at time of accident
 AIRMET TANGO for moderate turbulence and LLWS sfc-18000 expired 35 min before accident
 No PIREPs within ± 6 h and 20 mi radius of accident

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

Aircraft nosed over. Prop was severely bent, top of vertical stabilizer crushed, left wing bent downward, left wing struts buckled, cockpit frame slightly deformed, top of wing surfaces deformed

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Using topographic maps and satellite imagery, I located in a field on BLM land near Indian Creek Canyon where I hoped I could operate my aircraft while residing in a camper trailer. Field elevation was about 4800 MSL. I measured the field on satellite imagery and found that it offered over 1000' aligned roughly N-S in which to land and take off with no major obstacles on its north end, providing a factor of two margin over takeoff runs I have measured carefully using the runway stripes at airports at similar or greater takeoff weights and elevations at or above 4800 MSL.

Before attempting operations in the field, I drove to the site to inspect. The field is grass and widely spaced low shrubs on sandy loam. Footprints sink roughly a half inch into the ground and tire tracks from taxiing are roughly an inch deep. It contains some rises and dips with a few feet of vertical relief relative to the mean slope of the field. I measured the mean slope using GIS software to be 2.5% downhill to the north. I walked the field in person, looking for hidden terrain traps, and found its condition to be satisfactory in my judgement. My cohabitant, Murtidevi Nauth (Murti) and I moved our camper trailer to a site adjacent to the field.

On Friday, 11/6, I flew the aircraft to the field and landed to the south (upslope) successfully on the first attempt. The field felt bumpy and required a large amount of power (~75% throttle) to taxi uphill from a stop.

Knowing that I would wish to fly out of the field on Thursday, 11/12, possibly with my cohabitant Murti as passenger, I decided to take off solo from the field on the afternoon of Tuesday 11/10. My intent was that this would allow me to better assess risk before adding a passenger. I completed the takeoff toward the north without incident.

The aircraft has an issue with the flap lever in which it does not always lock securely into the 0° position. This became particularly apparent when taxiing on the bumpy ground, as the flap lever would quickly be knocked out of place and the flaps fall to the full down position. On the 11/10 takeoff, I held the lever throughout the takeoff to avoid inadvertent movement. This worked well but meant my right hand was not free for other adjustments. I used an aggressive takeoff technique common to bush field takeoffs in which I began with 0° flaps, then lowered flaps to the second notch once reaching takeoff speed to become airborne. All went smoothly.

After taking off on 11/10, I flew to U64 to practice short field operations without disturbing recreators in the Indian Creek area. At U64, I experimented with taking off using an initial -7° flap setting (intended for cruise in the Maule) so that the flaps would stay in place on bumpy terrain and my right hand could be kept free. I chose the negative flap setting instead of the first notch of positive flaps to minimize drag at the start of the takeoff run. All went well. I returned to the off-airport field by our camper and landed to the north (downslope) without any issues.

On the morning of Thursday, 11/12, my partner and I prepared to depart to U64 so that I could utilize better cellular signal there for a business meeting. I obtained weather online from the NOAA at the nearest station (BIVU1), but relied primarily on my own observation, including a makeshift windsock. Winds were light and from the south (I would guess 2-3 kts), skies were mostly overcast but with very high ceilings, well above the 10,000' mountain peaks visible to the south.

We untied and taxied to roughly the same position from which I had taken off on Tuesday, on the south side of the field. I decided to accept a slight tailwind and take off to the north primarily to take advantage of the downslope and avoid a small rise of rocks off the south end of the field. This also minimized any disturbance to popular campsites to the south.

RECOMMENDATION (How could this accident/incident have been prevented?)**Operator/Owner Safety Recommendation**

No major recommendations. Consider AD for worn Maule flaps levers on tailwheel aircraft. Accident could likely have been prevented with larger main tires, better field and takeoff path selection, and more aggressive control input to lower the tail when it was bumped upward early in the run.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☐ Yes ☒ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

15 Gallons

Fuel Type

☐ 80/87

☐ 115/145

☐ Jet B

☐ Other, specify _____

☒ 100 Low Lead

☐ Jet A

☐ JP8

☐ 100/130

☐ Jet A-1

☐ Automotive

Other Services, if Any, Prior to Departure**EVACUATION OF AIRCRAFT**

Was an emergency evacuation of the aircraft performed? ☒ Yes ☐ No

Method of Exit – Describe how the occupants exited and how many occupants evacuated each location

Pilot and passenger exited from their respective doors.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)

Aircraft Registration Number

Manufacturer: _____

Model: _____

Damage to Other Aircraft

☐ Destroyed

☐ Minor

☐ Substantial

☐ None

Registered Owner of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

Continuation of narrative:

I could tell the position where we lined up was not exactly the same as the one I had used on 11/10. The path ahead was less level. However, I could not remember precisely where I lined up on Tuesday and I deemed the path ahead sufficient, if not ideal. I have since walked the path and found the rises and dips to span a few feet in height and around two aircraft lengths.

Prior to the start of the takeoff run, we idled until the oil temperature reached 100 F. I then completed a standard run up, by which point the oil was near normal operating temperature. Unlike the 11/10 takeoff, I placed the flaps in the -7° position as I had practiced at U64 to minimize drag while ensuring the flaps would not inadvertently deploy due to bumps. Having found it difficult to raise the tail with the flaps in this position on my 11/10 practice takeoffs at U64, I added a quarter turn of forward trim from the takeoff mark to assist with raising the tail. I then opened the throttle and allowed the RPMs to reach about 2300 before releasing the brakes.

The take off run up until the few moments before we nosed over is hazy in my memory. I believe we began to bounce more than on my 11/10 take off early in the run. After we gathered some speed, I likely used forward yoke to try to catch and hold the tail off the ground, as I would normally do in a short field takeoff and had done on the successful 11/10 take off. However, I recall the tail getting quite high early in the run, causing me to feel alarmed. I feared the deceleration on soft dirt from aborting the takeoff would only push us further over, so I continued at full power hoping with speed I would gain sufficient control to lower the tail. In my memory, I never succeeded in lowering the tail and it only progressed from high to higher until we nosed over.

Marks in the dirt seem to indicate that the tail bounced a few times early in the run, then stayed in the air. The marks also seem to indicate that the mains left the ground several times, sometimes alternately though usually both together, though I have no memory of this. Murti confirms seeing the main on her side leave the ground at least once. The impressions of each contact get successively deeper. I conclude from this that we were doing something akin to porpoising as we approached nosing over.

The spacing of the rises and dips in the terrain is such that the tail was being pushed up by the crest of a rise at around the same time the mains were dropping and digging into a dip. I suspect this exacerbated the tail up forces early in the run.

As we gathered speed, tail high and getting higher, I reached down and began to lower the flaps. I hoped that we had enough speed that the flaps would get us in the air, off the bouncy terrain, and ultimately stabilized. However, in retrospect I believe this only increased our nose down attitude and was a grave mistake. In this aircraft, lowering flaps induces a nose down moment. In addition, it would have been difficult for me to reach the flaps lever while also holding the yoke hard back to try to lower the tail, especially with the flaps in their -7° position.

Near the wreck, the tire tracks go through a dip slightly deeper than the rest, and the left track goes through a small depression. This is soon followed by about a half dozen prop marks. I can remember hearing the prop slicing the ground several times before seeing it abruptly come to a halt. The prop marks in the ground then cease for a few yards, followed by one long deep mark joined at its end by a hole from where the spinner dug into the ground. The aircraft came to rest inverted just two or so yards further.

My memory of the nose over is of the aircraft abruptly halting as the spinner contacted the ground, flipping over, and hitting hard on the roof. Inverted and stopped, I became aware an alarm was sounding. I looked to Murti and saw she was bleeding but conscious. The fire extinguisher beneath my seat was lying on the roof, the screws of its mount having ripped free of the floor. Murti quickly unbuckled and exited through her door, which we believe had been forced open from the impact. I remained briefly in the aircraft, turning off the main switch before unbuckling, opening my door, and exiting.

I found Murti sitting down just a few yards from her door, clearly dazed. I checked on her, then returned to the aircraft out of concern that there was more I could do to make it safe. I reached into the cabin, turned off the ignition, removed the key, and shut off the fuel valve. I then checked on Murti again before reentering the aircraft for the third time to investigate the alarm, which I discovered was the ELT. I switched off the ELT.

Because this field was near our camper, we had access to a personal vehicle. We used this to drive to the Monticello hospital.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

11/15/2020

mm/dd/yyyy

Name of Pilot/Operator: Robert Oliver Parke Loyd

Signature:

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.
WPR21LA051

Reviewed by NTSB Regional Office
WPR

Name of Investigator
Eleazar Nepomuceno

Date Report Received
11/15/2020